SafetyBeltSafe U.S.A.

List of Recalls and Replacement Parts for Child Restraints

March 9, 2023

The latest recall is for certain Dorel/Maxi-Cosi/Safety 1st rear-facing-only safety seats. Some models are being recalled for the risk of a lower connector failure. Also, please see page 19 for information on the recall for seats noncompliant with FMVSS 213.

How can you tell if your safety seat is safe?

Make sure that the expiration date stamped on the plastic has not passed and it has never been used in a crash. You can't be sure about the history of a used seat unless you got it from a friend or relative. You will need the detailed instruction booklet (it can be ordered from the manufacturer if it is missing) to check that the seat has all of its parts and to find out how to use it correctly. Check for possible damage, such as cracks in the plastic, frayed straps, stiff buckles or harness adjusters. If the safety seat passes all of these criteria, you still need to check for possible recalls.

What is a safety seat recall?

Just like cars and other products, a safety seat may be "recalled" because of a defect that could injure your child. Manufacturers are required to fix the problem free of charge. If your seat is recalled, be sure to get it fixed right away.

Does the safety seat have to be sent back?

Not usually. Most problems can be fixed by replacing a part that the manufacturer will send you for free. Sometimes, with an older seat or when the company is out of business, you will need to take it to a special recycling center (go to www.carseat.org/recycling_la.html for more info) or, if none is available in your area, destroy the seat to make sure it is not picked up by someone and used by another child. Break it with a sledgehammer, crush it, or take it completely apart and mark it "not for use as a safety seat" before throwing it away wrapped securely in a heavy trash bag.

Should I keep using a recalled seat?

Many defects are minor, but some are quite serious. All problems should be corrected as soon as possible. Unless you have another seat, you should go on using the recalled one while you are waiting for the repair kit. Using a recalled safety seat almost always is safer than letting your child ride in a safety belt only.

How to check your safety seat for recalls

- 1. Look up the name of the manufacturer.
- 2. Look up the name of your specific model. Important: the model name may not be found anywhere on the seat, and many safety seats have similar model names. Some rear-facing-only seats are sold as a part of a stroller system. Since stroller model names are not included on this list, it is necessary to determine the name of the corresponding rear-facing-only seat to be sure all recalls and warnings have been found. Some manufacturers have style names (i.e., Oshkosh, Disney characters, etc.) sewn on the fabric or used in promotional materials. These names are used for more than one product and cannot be used to determine whether or not the seat has a recall. If you are not sure of the exact name of your seat, check the Color Pictorial Guide to Child Restraints (you may order a hard copy or license to print from SafetyBeltSafe U.S.A.) or contact the manufacturer or SafetyBeltSafe U.S.A. to help you identify it.
- 3. If you are sure of the EXACT name of your seat, you are ready to look it up on the recall list. Every model certified by the manufacturer to meet U.S. safety standards and made within the last 10 years is on this list, either with a recall or under the "no recall" section at the end of each manufacturer's section.
- 4. If your model has a recall listed, you need to compare the date of manufacture of your particular seat with the dates affected by the recall. The date is computer-generated on a paper sticker attached to the seat's side or back. Disregard dates on tags attached to the fabric cover or pre-printed in the corner of certification or instruction labels. For some recalls, you also will need to check the model number, which is found on the same sticker as the date. If the date sticker is missing or the date is not clearly marked, assume that all possible recalls apply to your seat. Even if no recall applies, do not use a seat if it has passed its expiration date (specified by the manufacturer in the instruction booklet, usually 4 to 10 years from the date of manufacture), which usually is stamped into the plastic shell.

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page 1 of 20

Special Features of the *SafetyBeltSafe* U.S.A. List of Recalls and Replacement Parts for Child Restraints

- 1. New recalls are added to this list as soon as they can be verified. Recall Update Service subscribers receive notifications by e-mail. To verify that a printed copy of this list is current, go to www.carseat.org and click on Recalls (left frame).
- 2. Voluntary customer notification campaigns, special warnings, and additional replacement parts available from manufacturers are included on the list. Some of these are not widely announced and are provided for the benefit of parents and child restraint checkers. The bracketed phrase [Not publicized] indicates usage advice or repair kit availability that has been verified with but not announced by the manufacturer. If a child restraint with one of these problems or any defect which has not been recognized with an official recall is found, it is important to notify officials responsible for defect investigations. To report a defect, call the National Highway Traffic Safety Administration (NHTSA) at 888-327-4236 or 800-424-9393 or go to http://www-odi.nhtsa.dot.gov/ivoq.
- 3. Recall wording, including manufacturer contact information, has been clarified and updated. The "Problem" is described clearly and briefly. The wording under "Action Needed" is based on current information supplied by the manufacturer instead of the original recall notice, which may contain ambiguous or obsolete information.
- 4. Model names are listed alphabetically. For ease of use and accuracy, all recalls are grouped by the model name of the restraint. Model numbers are also listed if provided by the manufacturer.
- 5. All child restraint models made in the past 10 years, with or without a recall, are listed (models without a recall are at the end of each manufacturer's section). If the model name is not found on the list, the child restraint should not be used.

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page **2** of 20

Child Restraint Manufacturer Recalls and Free Replacement Parts

	MODEL NAME	DATES		
MFR.	(MODEL #)	APPLICABLE	PROBLEM	ACTION REQUIRED
			15222 888-614-6667 www.4Moms	
	Self-Installing Car Seat (1032)	7/1/16 - 10/31/16		Call 4Moms at 888-614-6667 for a free replacement safety seat. BASE IS NOT AFFECTED.
4Moms models	with no recalls, rep	lacement parts	s, or warnings: none	
Aidia, Inc. 1459	18th St., San Franc	isco, CA 94107	866-328-8661 www.aidiaproduct	s.com
Aidia models wi	th no recalls, repla	cement parts, o	or warnings: Explorer, Pathfinder,	Scout.
www.angel-guai	rd.com	·	uting, 7001 Wooster Pike, Medina	
		<u> </u>	parts, or warnings: AngelRide Inf	ant Car Bed
			888-927-7422 www.aprica.com	
_			or warnings: none.	
,	- See Goodbaby U			
• 00			265 1-800-241-1848 www.babyjo	
7 66	City Go safety seats (BJ64510, BJ64529), bases (BJ80400, BJ61500), City Mini Travel Systems (BJ72510), Vue Lite Travel Systems (BJ70411, BJ70424,		Information on some labels, instruction manuals, and/or registration cards is missing, sized incorrectly, out of order, or has the wrong background color.	Call Baby Jogger at 800-241- 1848 for a free replacement safety seat.
	BJ70431)	s ranlacament	parts, or warnings: City Go 2, Cit	y Go Air City Turn City View
			761 800-328-7363 www.babytren	• •
Baby Trend	Hybrid LX 3-in-1 Centennial FB58181 and Kiwi	FB58181 mfd. on 7/23/16,	Center rivet on harness adjuster may fail if child weighs more than	Call 1-800-328-7363 for free
Baby Trend	Trendz Fastback 3-	10/1/11 to 7/31/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	
EZ Flex-Loc, EZ	EFlex-Loc 32, EZ-L	ift 35 Plus, EZ-1	parts, or warnings: Ally 35, Baby Loc, Euro Sport, Flex-Loc, Inertia, umi 2-in-1, Secure 35, Secure Snap	PROtect Elite, PROtect
Bergeron Healtl	h Care, 15 South S	econd Street, D	olgeville, NY 13329, 800-371-2778	8, www.adaptivemall.com
Bergeron model	with no recalls, re	placement part	ts, or warnings: Special Tomato	
Britax Child Sa	fety, 13501 So. Rid	ge Dr., Charlot	te, NC 28273, 888-427-4829, www	v.britaxusa.com
Britax	Advocate 70-G3 E9LG81A, E9LG83N, E9LG83P, E9LG83X, E9LG83Y, E9LL21A, E9LL23P, E9LL23Y	6/1/2012 to 8/31/2012	Material of HUGS chest pads is too soft, which could be a choking hazard.	Monitor child and call for
	Advocate ClickTight E1A025Q, E9LT95N, E9LT95Q, E9LT95Z	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page **3** of 20

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Britax	BOB B-Safe 35 All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	Boulevard 70-G3 E9LJ91A, E9LJ91M, E9LJ91S, E9LJ92E, E9LJ93P, E9LJ93S, E9LK91A	6/1/2012 to 8/31/2012	Material of HUGS chest pads is too soft, which could be a choking hazard.	Monitor child and call for replacement pads.
Britax	Boulevard ClickTight E1A015Q, E1A016A, E1A016H, E1A135Q, E9LT85Q, E9LT85S, E9LT86A, E9LT86F, E9LT86G, E9LT86H	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.
Britax	B-Safe 35 All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Travel System All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 Travel System All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Elite All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 Elite All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Elite Travel System All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	Marathon ClickTight E1A005R, E1A006B, E1A116L, E9LT71Q, E9LT75R, E9LT76B, E9LT76L, E9LT76N, E9LT76P, EXA116L	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.
Britax	Pavilion 70-G3 E9LK31A, E9LK31Q, E9LK32D, E9LK32Z, E9LK33Q, E9LL11A, E9LL11Q, E9LL12D, E9LL12Z	6/1/2012 to 8/31/2012	Material of HUGS chest pads is too soft, which could be a choking hazard.	Monitor child and call for replacement pads.

March 9, 2023 Page 4 of 20

	MODEL NAME	DATES		
MFR.	(MODEL #)	APPLICABLE	PROBLEM	ACTION REQUIRED

Britax models with no recalls, replacement parts, or warnings: Advocate, Advocate ClickTight ARB, Advocate 2013/G4, Boulevard ClickTight ARB, Boulevard 2013, B Safe, B Safe Gen 2, B Safe Gen 2 Fl;exFit, B Safe Gen 2 FlexFit Plus, B Safe Ultra, Dual Fit, Endeavours, Essentials Allegiance, Essentials Emblem, Essentials Skyline, Frontier 85, Frontier 85 SICT, Frontier 90, Grow with You ClickTight/ClickTight Plus, Highpoint, Highway, Highway 65, Marathon CS, Marathon 70 G3, Marathon 2013, Midpoint, One4Life Clicktight, Parkway (all models), Pavilion 2013, Pinnacle 90, Pioneer 70, Roundabout 50, Roundabout 55 G 3, Roundabout 2013, Skyline.

BubbleBum, 7380 Sand Lake Road, Suite 500, Orlando, FL 32819, 800-969-6586, www.bubblebum.us

BubbleBum models with no recalls, replacement parts, or warnings: BubbleBum Booster

Carfoldio 10685-B Hazelhurst Dr. #17695 Houston TX 77043 www.mifold.com

Carfoldio models with no recalls, replacement parts or warnings: Hifold, Mifold, Mifold Comfort, Mifold One, Mifold Sport

Car Seat Specialty - See Team-Tex America

Century Baby – See Graco

Chicco, 1842 William Penn Way, Ste. 101, Lancaster, PA 17601, 877-424-4226, www.chiccousa.com

Chicco models with no recalls, replacement parts, or warnings: Fit2, Fit4, Fold & Go i-Size, GoFit, GoFit Plus, KeyFit, KeyFit 30, KeyFit 30 Magic, KeyFit 35, KeyFit Strada, KidFit Booster, MyFit/LE/ZipAir, NextFit/IX/Sport, NextFit Zip/Max, NextFit Zip Air, One Fit

	rux, reath it zip riii,			
			ario M3B 2V9, Canada 866-656-2	
Clek	Fllo	All	Child may pick foam from	Clek will provide molded plastic
	FL15, FL!6, FL17,	manufactured	cushion under seat pad, creating a	insert that prevents access to the
	FL18, FL19		choking hazard.	foam, free of charge.
		2021		
Clek	Foonf	All	Child may pick foam from	Clek will provide molded plastic
	FO12, FO13,	manufactured	cushion under seat pad, creating a	insert that prevents access to the
	FO14,		choking hazard.	foam, free of charge.
	FO15, FO16, FO17,	2021		
	FO18, FO19.			
Clek		All	Small portion of canopy support	Clek will provide a replacement
Cion	Liing LG19U1		may break off, creating a choking	
			hazard.	
		September 15,		
		2020		
Clek	Liing	All	Labels on seat cover or infant	Clek will provide a replacement
	LG19U1		insert may come apart in small	seat cover or infant insert, free of
			pieces, creating a choking hazard.	cnarge.
		February 22, 2021		
Clek	Liingo		Small portion of canopy support	Clek will provide a replacement
	LGO20U1		may break off, creating a choking	canopy support, free of charge.
	2002001		hazard.	
		September 15,		
		2020		
Clek	Liingo	All	Labels on seat cover or infant	Clek will provide a replacement
	LGO20U1		insert may come apart in small	seat cover or infant insert, free of
		before February 22,	pieces, creating a choking hazard.	cnarge.
		2021		
Clek	Olli		Label showing correct installation	Clek will mail owners a new
	OL12U2	2020 – May 10,	is missing.	label, free of charge.
	OL1202	2022	-5.	,
Clek	Ozzi	March 1, 2020	Label showing correct installation	Clek will mail owners a new
		⊢ May 10, 2022	is missing.	label, free of charge.
Clek models	with no recalls, repl	acement parts, o	r warnings: Oobr	

[©] SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page 5 of 20

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
	ical – See also Inspi			
	· ·		rts, or warnings: #2000, #2500, S	. , ,
			harlotte, NC 28273, 800-992-662	
Combi	BabyRide 378099	May 1, 2016 to August 31, 2019		No remedy at this time. Contact Combi customer service by e-mail: customerservice@combiusa.com
Combi	Coccoro 8220	January 1, 2009 to December 31, 2012	Webbing (without seat) tore partially in static test because of embedded plastic button that keeps buckle tongues from sliding out of reach. Complete restraint system complies with all requirements.	Call 844-697-1690 for free harness replacement kit. Continue using seat until new harness is received.
Combi	Coccoro 8220	January 1, 2009 to June 29, 2016	lap-only belt, excessive force may be transferred to the child in a crash, increasing the risk of injury.	child's risk of injury during a crash.
33, Shuttle 35.			or warnings: Dakota, Kobuk, Ko	buk Air-Thru, Navette 22, Shuttle
	Fomy Internationa			
			CA 90503 844-876-6245, www.com	
	·		nent parts, or warnings: Carrot 3,	Carrot Booster Seat
	el Juvenile Group. baby International ine.com/US		Harrison Ave., Ste. 411, Boston	MA 02118 877-242-5676
Cybex	Aton	3/29/17- 1/4/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybex	Aton 2	3/29/17- 10/27/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybex	Aton M	3/7/18-11/1/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.

March 9, 2023 Page **6** of 20

Cybex	Aton Q	3/13/17-1/3/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybex	Cloud Q	7/6/17- 10/20/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybex	518000385, 518000387, 518002145, 518002149, 518002151, 518002153.	11/3/17- 8/31/18	Child may pick pieces of foam from safety seat headrest pad, creating a choking hazard.	Cybex will provide a kit with instructions on how to seal the headrest, free of charge.
			or warnings: Eternis, Sirona S, So ix, Solution Z Fix, X Fix Q	lution B-Fix, Solution B2 Fix+
Diono LLC, 418	8 Valley Ave. NW, S	Suite 100, Puya	llup, WA 98371, 855-463-4666, w	ww.diono.com
Diono	Cambria 2 31200-US-01 31201-US-01 31202-US-01	9/5/2020 to 11/30/20	Headrest may separate from backrest during a crash.	Diono will provide replacement backrest with headrest assembly free of charge. Call 855-463- 4666.
Diono	Olympia, Pacifica, Radian R100, Radian R120, Radian RXT, Rainier	11/25/13 to 9/5/17	If installed forward facing and untethered with lap-only belt, child may suffer chest injury in a crash.	Call 855-463-4666 for updated instruction manual, energy-absorbing pad, and new chest clip.
Monterey, Mont	ine Kids models wi	ey 5iST FixSafe	eplacement parts, or warnings: Ce, Monterey XT, Radian models 3Qer 2aX, Rainier 2aXT, Santa Fe, Sn	X, 30XT, 3r, 3rX, 3rXT, 3RXT
Dorel Juvenile	Group, 2525 State S	St., Columbus,	IN 47201, 800-544-1108, www.dj	gusa.com
	ne parent company for odels are marketed w		e Bauer, Maxi-Cosi, Safety 1st, Almes.	pna Lute, and Alpha Sport
Dorel China America	Babideal Storm Booster Seat BC901BPXL	2/28/19 only	Label attached to fabric cover may not have the required safety warnings and instructions.	Call 877-657-9546 for a compliant replacement cover.
Dorel	Dream Ride, Dream Ride Ultra	Many older sea unknown.	its have been recalled. Do not use i	f past expiration date or if date is
Dorel	Eddie Bauer	See specific mo	odel name.	
Dorel		Note: Dorel ide combination se harness; with o	entifies various models as "High Ba ats (used as child seat with harness r without armrest; with front or rea no harness included).	or as booster after removing

March 9, 2023 Page 7 of 20

Dorel	Maxi-Cosi Coral XP, IC313	5/1/20-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Maxi-Cosi Infant base, IC335	5/1/20-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new
Dorel	Maxi-Cosi Mico Luxe +, IC370		Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new
Dorel	Maxi-Cosi Mico XP, IC336, IC 338	9/1/20-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new
Dorel	Maxi-Cosi Mico XP Max, IC337	1/1/21-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new
Dorel	Maxi-Cosi Travel Systems	Adorra, Gia, Tayla, Zelia2 Max	May include Maxi-Cosi Mico XP model IC336 or IC338. If so, lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Maxi-Cosi Travel Systems	Mara XT, Tara XT	May include Maxi-Cosi Coral XP model IC313. If so, lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com

March 9, 2023 Page **8** of 20

Dorel	Maxi-Cosi Pria 70 CC133BGW, CC133BWI, CC133BWJI, CC133DCHI, CC133DCN	1/1/19 to 7/31/19	Failed FMVSS 213 when used with lap-only belt without tether strap attached for child over 65 lbs. Owners should be certain they have registered the seat with Dorel Juvenile Group.	Call 877-657-9546 to register seat & get free recall remedy kit with replacement instruction booklet and labels (forward-facing internal harness weight limit of the car seat to 65 lbs. and the height limit to 49 in.) Owners using or planning use for a child 65 lbs. or 40 in. or more can request free Maxi-Cosi Rodi Sport Booster (for children 40-100 lbs. & 43-57 in.)
Dorel	Maxi-Cosi Pria 85, Pria 85 Max: all models.	1/1/19 to 8/17/21	Failed FMVSS 213 for child over 65 lbs. when used with lap-only belt without tether strap attached. Owners should be certain they have registered the seat with Dorel Juvenile Group.	Call 877-657-9546 to register seat & get free recall remedy kit with replacement instruction booklet and labels (forward-facing internal harness weight limit of the car seat to 65 lbs. and the height limit to 49 in.). Owners using or planning use for a child 65 lbs. or 40 in. or more can request free Maxi-Cosi Rodi Sport Booster (for children 40-100 lbs. & 43-57 in.)
Dorel	Safety 1 st Secure Tech Infant base, IC372	All before 3/1/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Safety 1 st onBoard 35 Secure Tech, IC351		Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Safety 1st	See specific mo	odel name.	A. L. A.1. EX.C. A. L.

Dorel models with no recalls, replacement parts, or warnings: Able65, Advance 70 Air+, Advance EX 65 Air+, Advance SE or LX 65 Air+, Adjust 'n Go, Alpha Elite 65, Apex 65, Apt 40 RF, APT 50, Aquos 65, Boost A Pak, Boost Air Protect, Chart Air 65, Comfort High Back Booster, Comfort Ride, Comfy Convertible, Commuter, Complete Air 65, Complete Air 70, Complete Voyager, Continuum, Deluxe Backed BPB, Deluxe Harness 65, Deluxe Highback 65, Designer, Destination, Dream Ride SE, Easy Elite, EasyFit 65, Elite 80 Air+, Elite 100 Air +, enRoute, Essential Air, EverFit, Finale, Getaway, Go Hybrid, Grand Explorer, Grow and Go (all models), Guide 65, High Rider, Incognito, Light 'N Comfy, Maxi-Cosi Cosi 35, Maxi-Cosi Emme 360, Maxi-Cosi Magellan, Maxi-Cosi Magellan Max, Maxi-Cosi Magellan LiftFit, Maxi-Cosi Mico 30, Maxi-Cosi Mico Max Plus, Maxi-Cosi Mico Max 30, Maxi-Cosi Mico XP, Maxi-Cosi Prezi, Maxi- Cosi Pria 3-in-1 (65 lbs. ff), Maxi-Cosi Pria Sport, Maxi-Cosi Rodi (all models) Maxi-Cosi RodiFix, Maxi-Cosi RodiSport, Maxi-Cosi Romi, Maxi-Cosi Vello 65, Maxi-Cosi Vello 70, Mighty Fit 65 LX, DX 3-in-1, Multi Fit EX Air, onBoard 35 Air (all models), onBoard 35 LT, onSide Air Convertible, Protek, Rightway, Rise, Rumi Air, Scenera 40RF, Scenera Next, Scenera Versa-Fit OHB, Sport, Stack It!, Store 'N Go, Summit, Summit 65, Summit Deluxe, Top Side Booster, Traveler, Trio Fit, Ventura, Vista, XRS 65.

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page **9** of 20

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Dream On Me,	· · · · · · · · · · · · · · · · · · ·	orth, Piscatawa	ny NJ 08854, 732-748-1300, www.	dreamonme.com
Dream On Me booster, Mia Mo	models with no rec a oda Certo (see also re	alls, replacement ecall under Mia	nt parts, or warnings : Coupe back Moda)	less booster, Deluxe highback
sold in the U.S.	were withdrawn.		ecording to NHTSA, the manufactu	arer states that all of the boosters
	See Dorel Juvenile C			
www.evenflo.co	om	2 0,1	5 Byers Rd Miamisburg, OH 453	
Evenflo	Big Kid Booster 30911173AD, 3091967AD, 30911118AD, 30911120D	Unknown. Shipped 8/6/12 to 9/18/12	Registration card and instruction manual are missing. Sticker on backrest: "Display Only. Not intended for sale."	Call for missing card and manual. If seat has been distributed by program, notify recipient.
Evenflo	Chase, Chase LX, DLX, Chase Select 306xxxx, 329xxxx	8/23/11 to 3/3/14	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 800-490-7591 or go to www.buckle.evenflo.com for replacement buckle.
Evenflo	Embrace 35	12/2011- 5/2013. CHECK COLUMNS AT RIGHT FOR MODEL #'s	May be difficult to release harness buckle, which could cause risk to child in emergency. Model #'s 30711365, 31511040, 31511323, 31511400, 3151198, 3151953, 31521138, 46811205, 46811237, 48111200, 48111215, SEE COLUMN AT RIGHT FOR ADDITIONAL MODEL #s.	Call 800-490-7591 or go to www.embracebuckle.evenflo. com for replacement buckle. Additional model numbers: 48111215A, 48111218, 48111234, 48111235, 48111235A, 48111462, 48411391, 48411391D, 48411392, 48411504, 48411504D, 52911307A, 52921040, 55311138, 55311238, 55311292
Evenflo	Evolve 34411700	2/26/15 to 2/9/16	Child can reach & release button loosening seat harness, a risk for injury. If child has discovered how to release adjuster, stop using seat.	Call 800/233-5921 for free repair kit & front adjuster components.
Evenflo	Evolve 34411741	5/27/15 to 2/9/16	Child can reach & release button	Call 800/233-5921 for free repair kit & front adjuster components.
Evenflo	Express 329xxx	10/31/11 to 3/3/14	See Chase listed above for details.	
Evenflo	Fresh Air	_	c model name. Fresh Air is name o	
Evenflo	Maestro, Maestro Performance 310xxxx	8/22/11 to 10/17/13	See Chase listed above for details.	
Evenflo	LX, 65 DLX	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.
Evenflo		3/4/13 to 8/26/13	See Chase listed above for details.	

[©] SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page 10 of 20

MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Secure Kid, Secure Kid LX, DLX, 100/300/400, 308xxxx	12/13/11 to 3/3/14	See Chase listed above for details.	
SureRide, SureRide Deluxe, Titan 65	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.
SureRide DLX 371xxxx	6/20/12 to 10/17/13	See Chase listed above for details.	
Symphony 65, 65 E3, LX, DLX	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.
Symphony 65, 65 E3, LX, DLX 345xxxx, 346xxxx	10/2/12 to 8/26/13	See Chase listed above for details.	
Titan 65 71xxxx	6/20/12 to 10/17/13	See Chase listed above for details.	
Transitions 34411686, 34411695,	12/18/14 to 1/29/16	Child can reach & release button loosening seat harness, a risk for injury. If child has discovered how to release adjuster, stop	Call 800/233-5921 for new bottom seat pad & front adjuster components. Important: view video at
	(MODEL #) Secure Kid, Secure Kid LX, DLX, 100/300/400, 308xxxx SureRide, SureRide Deluxe, Titan 65 SureRide DLX 371xxxx Symphony 65, 65 E3, LX, DLX Symphony 65, 65 E3, LX, DLX 345xxxx, 346xxxx Titan 65 71xxxx Transitions	CMODEL #) APPLICABLE	Secure Kid, Secure Kid LX, DLX, 100/300/400, 308xxxx

Evenflo models with no recalls, replacement parts, or warnings: Advanced LiteMax 35, All4One, All4One DLX, Amp, Chase 2-in-1, Chase Plus 2-in1, Embrace 35 Advanced (w/SensorSafe), EveryFit/Every Kid, Every Stage DLX, Generations, Generations 65, GoTime, LiteMax 35, LiteMax DLX, LiteMax Sport, Maestro Sport, Nurture, NurtureMax, ProSeries LiteMaxRight Fit (all models), Revolve 360, SafeMax All-in-One, SafeMax RFO, SecureRide 35, Serenade, Sightseer (highback booster), Sonus 50, Sonus 65, Spectrum, Stratos, Titan Elite, Titan Sport, Traditions, Tribute Sport, Triumph Advance 50, Triumph Advance 65, Vision.

EZ-ON Products LLC, 605 Commerce Way West, Jupiter, FL 33458, 800-323-6598, www.ezonpro.com EZ-ON Products LLC models with no recalls, replacement parts, or warnings: Vests and Harnesses

GOBOOSTER – All models sold within US have been withdrawn, per NHTSA.

Goodbaby USA 560 Harrison Ave. Boston MA 02118 844-543-2020 GBchildusa.com

Goodbaby USA models with no recalls, replacement parts or warnings: Asana 35, Asana 35AP, Asana 35 DLX/LTE, Idan, Phil&Teds Alpha Protect, Aria Child/Urbini Asenti, Urbini Omni, Urbini Petal, Urbini Presti, Urbini Touri, Urbini Sonti.

Graco Children's Products, 150 Oaklands Blvd, Exton, PA 19341, 800-345-4109 www.gracobaby.com. May be difficult to release harness Call 877-766-7470 for Graco Argos 70, Argos 70 5/1/11 to Elite 7/31/13 buckle, which could cause risk to replacement buckle, or visit GracoBuckleRecall.com child in emergency. Call 1-800-345-4109 for Graco Classic Ride 3/1/ 14 to Labels missing information on replacement label. 2/28/15 location of instruction manual. 1812930 Classic Ride 50 10/1/11 to 9/30/13; see Argos 70 listed above for details. Graco Labels missing information on Call 1-800-345-4109 for Graco ComfortSport 3/1/ 14 to location of instruction manual. replacement label. 1794333, 1813040 2/28/15 ComfortSport 10/1/10 to 9/30/13; see Argos 70 listed above for details. Graco

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page 11 of 20

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Graco	Extend2Fit 1954477	11/27/15 to 1/20/16	Information on recline label (upright for infant; reclined for older child) risks injury. Check labels on sides of seat to determine that one side is all English, other side, all Spanish.	If languages are mixed on either side of seat, call 1-800-345-4109 for replacement label.
Graco	Head Wise 70 w/Safety Surround	1/1/12 to 7/31/	13 and 8/3/13; see Argos 70 listed	above for details.
Graco	Milestone 191030, 1923980, 1926538, 1926539	7/9/15 to 10/9/15	Label missing directive to install child restraint using lower anchors or safety belt.	Contact Graco at 800-345-4109 for free replacement label.
Graco	My Ride 65, My Ride 65 with Safety Surround	4/1/09 to 7/31/	13, and 9/30/13; see Argos 70 listed	l above for details.
Graco	My Ride 65	1813074 (mfd. 7/5/14-7/24/14) and 1908152 (rharness tag. Th	334 (mfd. 5/20/14-7/15/14), 18130 6/20/14-7/27/14), 1853478 (mfd. 7), 1872691 (mfd. 5/16/14-8/1/14), 1 mfd. 7/23/14-7/27/14). Affected morese harnesses may fail in a crash. Crness. 800-345-4109	7/11/14-7/27/14), 1871689 (mfd. 877535 (mfd. 5/26/14-7/27/14), odels also have "2014/06" on
Graco	My Ride 70		; See Argos 70 listed above for deta	nils.
Graco	My Size 70	1/1/12 to 7/31/	13, and 8/3/13; see Argos 70 listed	above for details.
Graco	Nautilus 3-in-1, Nautilus Elite, Nautilus Plus	10/1/07 to 7/31/13 and 8/19/13; see Argos 70 listed above for details.		
Graco	Ready Ride 1924519, 1924520	3/1/ 14 to 2/28/15	Labels missing information on location of instruction manual.	Call 1-800-345-4109 for replacement label.
Graco	Ready Ride	10/1/10 to 9/30/13	See Argos 70 listed above for details.	
Graco	Size4Me 70	1/1/12 to 7/31/	13 and 8/3/13; see Argos 70 listed a	above for details.
Graco	Smart Seat	12/1/10-9/30/13	3 and 10/9/2013, 12/25/2013, 1/10/	2014; see Argos 70 listed above.
Graco	SnugRide, SnugRide Classic Connect	3/1/11 to 5/31/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 877-766-7470 for replacement buckle.
Graco	SnugRide 30, SnugRide Classic Connect 30	7/1/10 to 1/31/13	See SnugRide, SnugRide Classic Connect listed above for details.	Call 877-766-7470 for replacement buckle.
Graco	SnugRide 35, SnugRide Classic Connect 35	5/1/11 to 1/31/13	See SnugRide, SnugRide Classic Connect listed above for details.	Call 877-766-7470 for replacement buckle.
Graco	SnugRide Click Connect 40	6/1/12 to 12/31/12	See SnugRide, SnugRide Classic Connect listed above for details.	Call 877-766-7470 for replacement buckle.
Graco	TurboBooster 1963973	3/8/16 to 4/2/16	Instructions don't state that booster must be securely belted to vehicle at all times, even when booster is not occupied.	Call 800-345-4109 for revised instruction booklet.

March 9, 2023 Page **12** of 20

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED	
Graco	TurboBooster 1963974	12/22/15 to 3/30/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.	
Graco	TurboBooster 1963975	12/22/15 to 3/17/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.	
Graco	TurboBooster 1963976	2/17/16 to 3/24/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.	
Graco	TurboBooster 1967886	1/13/16 to 4/5/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.	
Graco TurboBooster 3/29/16 See reason at TurboBooster Call 800-345-4109 for revised 1975173 Call 800-345-4109 for revised instruction booklet.					

Graco models with no recalls, replacement parts, or warnings. 4Ever (all models), Affix, Affix w/Safety Surround, Argos 65, Argos 80 Elite, Assura, Atlas 65, Babyjogger CityTurn, Century Baby BoostOn, Century Baby Carry On 35, Century Baby Carry On 35 LX, Century Baby Drive On, Colorz, Connext, Contender 65, Contender Go, Contender Slim, Extend2Fit Platinum, Extend2Fit 3-in1, Extend2Fit 3-in-1 w/Anti Rebound Bar, Platinum, Extend2Fit True Shield 3-in1, Fit4Me 65, Grows4Me, Head Wise 65, Infant Safe Seat, Landmark/Milestone 3-in-1, MySize 65, Nautilus 65 LX/DLX, Nautilus 80 Elite, Nautilus SnugLock Grow, Nautilus 2.0 LX, Nautilus, Premier SnugRide SnugFit 35 Elite, Premier SnugRide SnugFit LoadLeg, Sequence 65 Platinum, SnugLock DLX, Recline N' Ride, RightGuide Seat Belt Trainer, Sequel 65, Sequence 65, Size4Me 65, SlimFit 3-in-1, SlimFit 3 in 1 Platinum, SnugRide Click Connect 30, SnugRide Click Connect 35, SnugRide SnugLock 30, SnugRide 35 Lite, SnugRide Lite Elite, SnugRide SnugFit 35, SnugRide SnugLock 35 (all models), SnugRide SnugLock Extend2Fit, Tranzitions, Tranzitions SnugLock 3-in-1, TrioGrow SnugLock, TriRide, TurboBooster TakeAlong, TurboBooster Grow, TurboBooster LX backless LATCH, TurboBooster Stretch, TurboBooster TakeAlong, TurboBooster 2.0 LX, Turn2Me.

Harmony Juvenile Products,	1600 53rd Street,]	North Bergen, N	NJ 07047, 877-306-1001,
www.harmonviuvenile.com	,	6 /	,

Juvenile 6/24/17 forces which could occur to a child during a crash. at 877/306-1001 for next steps.	- ·· ·	Big Boost Deluxe	6/24/17	forces which could occur to a	Call Harmony customer service at 877/306-1001 for next steps.
--	--------	------------------	---------	-------------------------------	---

Harmony models with no recalls, replacement parts, or warnings: Baby Armor, Carpooler, Cruz, Defender 360, Dreamtime Comfort, DreamTime Elite with LATCH, Folding Travel Booster, LiteRider, Olympian, Transit, Transit Deluxe, V6 Highback, Youth Booster, Youth Booster Elite with LATCH.

hauck Fun for Kids, 212 A Wilkinson Rd., Brampton, Ont., L6T 4M4 Canada 905 455 5888

hauck Fun for Kids models with no recalls, replacement parts, or warnings: iCoo, iGuard, PROsafe 35

hiccapop, 160 Alamo Plaza, Unit 590, Alamo CA 94507 888-442-2266 www.hiccapop.com

hiccapop models with no recalls, replacement parts, or warnings: UberBoost

IMMI (Also See SafeGuard) 18881 IMMI Way Westfield, Indiana 46074 317-896-9531 www.imminet.com

IMMI Models with no recalls, replacement parts or warnings: Go Combination Child Seat

Inspired by Drive 11724 Willake St. Santa Fe Springs CA 90670 800-454-6612 www.inspiredbydrive.com

Inspired by Drive models with no recalls, replacement parts or warnings: Spirit, Spirit APS, Spirit IPS, Spirit Plus

Jané USA, P.O. Box 410007, San Francisco, CA 94141, 415-824-1237, www.janeusa.com

Jané USA models with no recalls, replacement parts, or warnings: Indy Plus, Montecarlo R1, Team Plus

Jeffco or LaRoche models with no recalls, replacement parts, or warnings: Grizzly Bear, Polar Bear, Teddy Bear

J J Cole - See Tomy

Kiddy, http://www.kiddy.de/blog/us/info@kiddyuk.com

,	<u> </u>	<u> </u>		
Kiddy USA	World Plus		Buckle tongue may not fully	Contact manufacturer for full
·	51 100 WP	10/5/13 (all	engage on affected seats.	refund of purchase price. Call
		models ever		1-855-925-4339 for more
		produced)		information.

Kiddy models with no recalls, replacement parts, or warnings: Cruiserfix Pro, Cruiser 3

KidsEmbrace, 4830 Rusina Rd., Suite B, Colorado Springs, CO 80907, 866-947-3287, www.kidsembrace.com

KidsEmbrace models with no recalls, replacement parts, or warnings: Combination seat, Toddler Booster, Fun Ride

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page 13 of 20

	T	T	T	1		
MED	MODEL NAME	DATES	DDON EM	A CITION DECLUDED		
MFR.	(MODEL #)	APPLICABLE	PROBLEM	ACTION REQUIRED		
			GA 30305 770-551-0442 www.kid			
		piacement pa	rts, or warnings: Ingenuity InTi	rust 35		
LaRoche - See J						
U	e - See Tomy Intern					
			74 317-804-9160 www.lilfan.com			
Lil Fan models	with no recalls, rep	lacement parts	, or warnings: Box Seat, Club Sea	at		
Lilly Gold 5468	Maple Ridge Ct., N	Ainnetonka MI	N 55343 800-829-1625 www.lillyg	old.com		
Lilly Gold prod	ucts with no recalls	, warnings, or	replacement parts: Sit 'N' Stroll			
			300-321-0183 www.littletikes.com			
Little Tikes pro	ducts with no recal	ls, warnings or	replacement parts: Highback Bo	oster, Backless Booster, Hip		
Maxi-Cosi - See	Dorel					
			polis, IN 46217, 317-409-0148, w	ww.merrittcarseat.com		
	\mathcal{C}	8/8/19 to	Harness may not be sewn	Call 317/409-0148 to order free		
Manufacturing	Bed	10/24/19	properly where buckle is attached.	replacement harness.		
		no recalls, repla	acement parts, or warnings: Cham	berlain, Churchill, Hope Car Bed,		
Jefferson, Roosev						
	m Tex America	101 81	D. 10742 077	(0)(0)=0		
Nuna Baby Essentials Inc., 70 Thousand Oaks Blvd., Morgantown, PA 19543, 855-686-2872 www.nuna.eu/USA/index						
Nuna model wit Pipa Lite R, Pipa	th no recalls, replace Lite RX, Pipa RX,	ement parts, o Pipa Urbn, Rava	r warnings: AACE, Exec, Pipa, Pi a, Revv, Relx (base for Pipa RX an	pa Lite, Pipa Lite LX, ad Pipa Lite R)		
Orbit Baby Inc.	, 5437 Central Ave	nue, Suite 10, N	Newark, CA 94560, 877-672-2229	, www.orbitbaby.com		
Orbit Baby		3/20/13 to	StrongArm knob may detach or	Call to order repair kit. Use seat		
	ORB822000, Batch	7/20/13	spin without tightening base.	without base until base is		
	#A0840, A0860, A0880			repaired.		
	models with no red		ents parts, or warnings: Infant G2	/Infant G3, Infant G5, Orbit		
Toddler/Toddler G2/Toddler G3 (see above for information about bases), Toddler G5						
Peg Perego U.S.	Peg Perego U.S.A., 3625 Independence Dr., Fort Wayne, IN 46808, 800-671-1701, us.pegperego.com					
Peg Perego	Primo Viaggio	All models	Stroller use: To prevent possibility	y of baby's fall due to incorrect		
		with stroller		te sure that front bar is installed on		
		base that has front bar	stroller and that seat is latched firm Test by yanking seat toward front			
Peg Perego models with no recalls, replacement parts, or warnings: Primo Viaggio 4-35, Primo Viaggio 4-35 Nido,						
Primo Viaggio Convertible, Primo Viaggio Convertible Kinetic, Primo Viaggio Lounge, Primo Viaggio SIP ES 30-30, Primo Viaggio SIP 5-70, Viaggio Flex 120, Viaggio Shuttle Plus						
Phil&Teds – See Goodbaby						
Porsche Cars of North America. Contact Britax.						
	Porsche models with no recalls, replacement parts, or warnings: Baby Seat, Junior Seat G1, Junior Seat Plus G2, G3.					

March 9, 2023 Page **14** of 20

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED		
	ProRider 7818 S 212th St Ste. 106, Kent, WA 98032 800-414-5560 www.prorider.com					
ProRider mod	el with no recalls, re	placement part	ts, or warnings: CNS Booster			
R82 (ETAC), 2	830 California St., T	Torrance, CA 9	0503 844-876-6245, www.convaid	d.com		
R82 (ETAC) m	nodels with no recall	s, replacement	parts, or warnings: Pilot, Quokka	a, Stingray Swing-out, Wallaroo		
Recaro Child Sus.recaro-cs.co	• •	n America, 160	0 Harmon Rd., Auburn Hills, Ml	48326, 888-973-2276		
Recaro	Performance RIDE, all models beginning with 333.01	1/15/13 to 6/9/15	Tether may detach from car seat during crash.	Retrofit kit will be provided by Recaro. Customers may also call 1-866-628-4750 to request retrofit kit.		
Recaro	ProRIDE, all models beginning with 332.01	4/9/10 to 6/9/15	Tether may detach from car seat during crash.	Retrofit kit will be provided by Recaro. Customers may also call 1-866-628-4750 to request retrofit kit.		
Recaro	ProSport (model numbers start with 385)	1/31/13	Excess head excursion if restraint is installed with lower anchors and not tethered.	Call mfr. for label & revised instructions; discontinue use of lower anchors when child reaches 40 lbs.		
ProBooster, Pro Safe Traffic Sy Safe Traffic Sy booster, Travels	Performance Crossover, Performance Racer/Rally, Performance Ride, Performance Roadster, Performance Sport, ProBooster, ProRide, Vivo, Vivo Lite. Safe Traffic System Inc., 10201 Pacific Ave. Franklin Park IL 847-233-0365, www.safetrafficsystem.com Safe Traffic System models with no recalls, replacement parts, or warnings: Ride Safer Vests (all sizes), Delighter booster, TravelSmarter Booster					
SafeGuard, 18	881 US 31 North, P.O	O. Box 408, We	estfield, IN 46074, 800-586-7839, arts, or warnings: SafeGuard, Saf	www.safeguardseat.com		
			n Beach, FL 33474, 561-732-1233			
Safety Angel/S	nodel with no recall:	Ride Ryte	II Beach, FL 33474, 301-732-1233	s, www.saietyangei.com		
-	Dorel Juvenile Grou					
	ton Rolyan, 1000 Re		Bolingbrook, IL 60440, 800-323-	5547,		
Sammons Pres	ton Rolyan models v	vith no recalls,	replacement parts, or warnings:	Tumble Forms Carrie Seats		
			NJ 07508 862-240-1755 www.hapj	pykidssmartparents.com		
	<u> </u>	· · · · · · · · · · · · · · · · · · ·	ngs or replacement parts: Doona			
www.sentryba	byproducts.com	ŕ	0470 Colorado Springs CO 80919			
Sentry Baby Products models with no recalls, replacement parts, or warnings: Guardimals smartridr 1321 Upland Dr., Ste. 10963 Houston TX 77043 800-317-8029 www.whizrider.com						
smartridr smartridr						
	· · · · · · · · · · · · · · · · · · ·		rts, or warnings: none			
			8106, 800-336-7684, www.R82.com			
Snug Seat models with no recalls, replacement parts, or warnings: Hippo, Pilot, SS1000, Snug Seat Car Bed, Traveler Plus EL						

March 9, 2023 Page **15** of 20

	MODEL NAME	DATES					
MFR.	(MODEL #)	APPLICABLE	PROBLEM	ACTION REQUIRED			
Snugli, 225 Byers Rd Miamisburg, OH 45342, 1-800-374-3603, www.snugli.com							
Snugli	All-in-One	2011-2015, select models	strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.			
Snugli	All-in-One 346xxxx	10/2/12 to 8/26/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 800-490-7591 (Evenflo) or go to www.buckle.evenflo.com for replacement buckle.			
Snugli	Booster 308xxxx	12/13/11 to 3/3/14	See All-in-One				
	· A		or warnings: Infant Car Seat				
			tet, RI 02895, 800-268-6237, www				
Summer Infant			ent parts, or warnings: Affirm 335	S, Prodigy			
MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED			
	` •		, P. O. Box 3194, Rock Hill, SC 2				
Team-Tex mode	els with no recalls, 1	replacement pa	rts, or warnings: Beline, Dream, 1	Dreamway SP, HighRide			
,			PA 19341, 877-838-8664, www.teu				
Teutonia model	s with no recalls, re	eplacement par	ts, or warnings: T-Tario 32, T-Tari	rio 35			
(previously Exo	Thomashilfen, 309 South Cloverdale Street, Unit B 12, Seattle WA 98108, 866-870-2122, www.thomashilfen.com (previously Exomotion)						
Distributor for Recaro Monza Nova 2 Reha, Recaro ProSport Reha, Recaro Defender Reha (no recalls)							
(previously Lea	rning Curve)	•	20, Oak Brook, IL 60523, 1-800-7	•			
Tomy, Learning Curve, and Compass models with no recalls, replacement parts, or warnings: Via (all models), Compass Folding Adjustable Boosters (all models), all True Fit convertible models							
Triple Play Pro	ducts - See Lilly Go	old					
UPPAbaby, 60	Sharp Street, Hingl		3, 781-413-3000 www.uppababy.c				
	WPPAbaby Knox 2019 to 2020 UPPAbaby voluntarily recalled the first Knox models (manufactured 2019 to 2020), because it was found to easily tip over when installed rearfacing. UPPAbaby offered a refund and pulled all Knox seats off the shelf. A redesigned version was released in 2021.						
		replacement p	arts, or warnings: Alta, Mesa, Me	esa V2			
Urbini – See Go	•						
		+	a CA 91030 888-924-9292 wayb.c				
	WAYB Pico 2/1/19 to 8/23/19 Stop using if headrest tubes or pins connecting to tubes are broken or cracked. Call 888/924-9292 for a redesigned headrest. Manufacturer states breakage occurs due to damage in transit outside the vehicle or overloading in installation or use.			a redesigned headrest. ars due to damage in transit			
WAYB models with no recalls, replacement parts, or warnings: none							

March 9, 2023 Page **16** of 20

BMW of North America is recalling 7,162 2016 BMW 5 Series sedans to fix a problem with the child-restraint lower anchor system. The 2016 BMW 5 Series models are listed on the following page. The affected vehicles have an inboard lower anchor for child restraints on the left rear seat that may have been bent downwards, preventing the child seat from fully engaging both lower anchors, thus, increasing a child's risk of injury in a crash. The month and year of manufacture can be found on the VIN sticker on the inside driver door panel. Caregivers installing a restraint here should use the safety belt instead, until the lower anchor is inspected/repaired by BMW.

BMW of North America announced an additional recall on July 12, 2016 affecting certain X3 and X4 models, manufactured between 2011 and 2016. Please see table below.

<u>Nissan North America</u> has announced a recall on its 2013-2016 Sentras. Please see table on following page.

<u>Volkswagen North America</u> has announced a recall on some model year 2018 Atlas SUVs. Please see table on following page.

BMW of North America, LLC	528i Sedan	8/15/15 to 9/14/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	528i xDrive Sedan	7/20/15 to 9/11/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535i Sedan	7/20/15 to 9/8/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC		9/9/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535d xDrive Sedan	7/21/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	550i Sedan	7/20/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	550i xDrive Sedan	7/20/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	535d Sedan	7/20/15 to 9/8/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	M5 Sedan	7/21/15 to 9/11/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	X3 xDrive28d	2015-2017 model year, manufactured 3/10/14 to 3/31/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525- 7417.

March 9, 2023 Page **17** of 20

[©] SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

	X3 xDrive28i, X3 xDrive35i	model year, manufactured 7/2/10 to	damaged if child restraint is	Owners should contact BMW Customer Service at (800) 525- 7417.
BMW of North America, LLC	X4 xDrive35i, X4 xDriveM40i	manufactured 3/3/14 to	damaged if child restraint is	Owners should contact BMW Customer Service at (800) 525- 7417.
Nissan North America, Inc.		model year (approximately 620,000	belt bracket may become deformed if child restraint is	As of 5/8/16, Nissan North America, Inc. has not found a solution for the problem. Do not install any child restraint in this seating position.
Volkswagen North America	2 nd row bench seats	year, manufactured 11/7/16 to 6/5/18 (approximately 54,357 vehicles)	warning to avoid installing safety seats with rigid lower	Dealers will inspect and possibly replace such buckles and give an owner's manual supplement on child passenger safety.

March 9, 2023 Page **18** of 20

Switchable Retractor Recall

Some Autoliv switchable retractors in a variety of 2021 and 2022 vehicles and manufactured between October 26, 2020, and January 27, 2021 do not stay locked when switched to automatic locking mode. Take the vehicle back to the dealership for a free repair.

Temporarily, use a different seating position OR use with the lock-off on your safety seat OR if the child's weight is under that listed for your safety seat lower connectors, connect to the lower anchors, and always attach the top tether strap for any forward-facing safety seat.

The following 2021 and 2022 vehicles and seating positions are affected:

- 2021 **Audi** S3, A4, S4, A6, S6, RS6, A7, S7, RS7, A8, and S8 sedans (middle rear seat belts only)
- 2021 **Audi** A5, S5, and RS5 coupes and convertibles, and A6 Allroad wagons (middle rear seat belts only)
- 2021 Audi Q3, Q5, SQ5, Q7, SQ7, Q8, SQ8, RSQ8, and E-Tron SUVs (middle rear seat belts only)
- 2021 **Bentley** Bentayga SUVs (front passenger belt only)
- 2021 **BMW** 2 Series, 3 Series, M3, 4 Series, M4, and 5 Series sedans, coupes, and convertibles
- 2021 BMW X1 and X2 SUVs
- 2021 **BMW** Z4 coupes (front passenger seat only)
- 2021/2022 **Ford** Transit and Ford Transit Connect SUVs (front passenger belt only)
- 2021 Lamborghini Urus SUVs (middle rear belt only)
- 2021 **Mini Cooper** and Mini Clubman hatchbacks and convertibles (front passenger seat only)
- 2022 Mitsubishi Outlander SUVs (front passenger and second-row belts)
- 2021 **Nissan** Rogue Sport SUVs (front passenger and rear outer belts only)
- 2021 **Porsche** 911 coupes and convertibles
- 2021 **Porsche** Panamera and Taycan sedans
- 2021 **Rolls-Royce** Cullinan SUVs
- 2021 Rolls-Royce Ghost and Phantom sedans
- 2021 **Toyota** Supra coupes (front passenger seat only)
- 2021 **Volkswagen** ID.4 SUVs (rear seat belts only)

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page **19** of 20

Recalls for Safety Seat Products Noncompliant with FMVSS 213

December 29, 2022: JD E-Commerce America Limited (Joybuy Express). NHTSA has determined a recall on all Marainbow Portable Infant Safe Seat **and materially similar child seats**. The installation labels display incorrect instructions. The seat design prohibits these models and all similar from being installed properly. As such, these seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard 213, "Child Restraint Systems." The seat may be improperly installed, increasing the risk of injury in a crash. **Joybuy Express** will provide a refund to purchasers. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Joybuy Express customer service at 1-302-426-4543.



- 1. CARTOON STROLLER CUSHION
- 2. FARFI RUST-PROOF BOOSTER
- 3. FOLD WATERPROOF CAR SEAT
- 4. MARINBOW PORTABLE INFANT
- 5. PORTABLE BABY COVER SEAT
- 6. PORTABLE BABY SAFETY SEAT
- 7. PORTABLE INFANT SAFE SEAT
- 8. PRETTY COMY CAR SEAT
- 9. PRETTY COMY PORTABLE SEAT
- 10. QCTIME ANTI-SLIP CUSHION
- 11. THICK PORTABLE CAR SEAT
- 12. TWOWOOD ANTI-SLIP CUSHION
- 13. TWOWOOD RUST-PROOF BOOSTE[R]
- 14. YDX ANTI-SLIP CUSHION

© SafetyBeltSafe U.S.A. 27943 Seco Canyon Rd., Unit 301, Santa Clarita CA 91350 www.carseat.org (800) 745-SAFE

March 9, 2023 Page **20** of 20