

## **List of Recalls and Replacement Parts for Child Restraints**

**June 27, 2024**

There is no new recall. New seats have been added. Also, please see page 17 for information on the recall for child restraints noncompliant with FMVSS 213.

### **How can you tell if your safety seat is safe?**

Make sure that the expiration date stamped on the plastic has not passed and it has never been used in a crash. You can't be sure about the history of a used seat unless you got it from a friend or relative. You will need the detailed instruction booklet (it can be ordered from the manufacturer if it is missing) to check that the seat has all of its parts and to find out how to use it correctly. Check for possible damage, such as cracks in the plastic, frayed straps, stiff buckles or harness adjusters. If the safety seat passes all of these criteria, you still need to check for possible recalls.

### **What is a safety seat recall?**

Just like cars and other products, a safety seat may be "recalled" because of a defect that could injure your child. Manufacturers are required to fix the problem free of charge. If your seat is recalled, be sure to get it fixed right away.

### **Does the safety seat have to be sent back?**

Not usually. Most problems can be fixed by replacing a part that the manufacturer will send you for free. Sometimes, with an older seat or when the company is out of business, you will need to take it to a special recycling center (go to [www.carseat.org/recycling\\_la.html](http://www.carseat.org/recycling_la.html) for more info) or, if none is available in your area, destroy the seat to make sure it is not picked up by someone and used by another child. Break it with a sledgehammer, crush it, or take it completely apart and mark it "not for use as a safety seat" before throwing it away wrapped securely in a heavy trash bag.

### **Should I keep using a recalled seat?**

Many defects are minor, but some are quite serious. All problems should be corrected as soon as possible. Unless you have another seat, you should go on using the recalled one while you are waiting for the repair kit. Using a recalled safety seat almost always is safer than letting your child ride in a safety belt only.

### **How to check your safety seat for recalls**

1. Look up the name of the manufacturer.
2. Look up the name of your specific model. Important: the model name may not be found anywhere on the seat, and many safety seats have similar model names. Some rear-facing-only seats are sold as a part of a stroller system. Since stroller model names are not included on this list, it is necessary to determine the name of the corresponding rear-facing-only seat to be sure all recalls and warnings have been found. Some manufacturers have style names (i.e., Oshkosh, Disney characters, etc.) sewn on the fabric or used in promotional materials. These names are used for more than one product and cannot be used to determine whether or not the seat has a recall. If you are not sure of the exact name of your seat, contact the manufacturer or SafetyBeltSafe U.S.A. to help you identify it.
3. If you are sure of the EXACT name of your seat, you are ready to look it up on the recall list. Every model certified by the manufacturer to meet U.S. safety standards and made within the last 10 years is on this list, either with a recall or under the "no recall" section at the end of each manufacturer's section.
4. If your model has a recall listed, you need to compare the date of manufacture of your particular seat with the dates affected by the recall. The date is computer-generated on a paper sticker attached to the seat's side or back. Disregard dates on tags attached to the fabric cover or pre-printed in the corner of certification or instruction labels. For some recalls, you also will need to check the model number, which is found on the same sticker as the date. If the date sticker is missing or the date is not clearly marked, assume that all possible recalls apply to your seat. Even if no recall applies, do not use a seat if it has passed its expiration date (specified by the manufacturer in the instruction booklet, usually 4 to 10 years from the date of manufacture), which usually is stamped into the plastic shell.

**Special Features of the *SafetyBeltSafe* U.S.A.  
List of Recalls and Replacement Parts for Child Restraints**

1. New recalls are added to this list as soon as they can be verified. Recall Update Service subscribers receive notifications by e-mail. To verify that a printed copy of this list is current, go to [www.carseat.org](http://www.carseat.org) and click on Recalls (left frame).
2. Voluntary customer notification campaigns, special warnings, and additional replacement parts available from manufacturers are included on the list. Some of these are not widely announced and are provided for the benefit of parents and child restraint checkers. The bracketed phrase [Not publicized] indicates usage advice or repair kit availability that has been verified with but not announced by the manufacturer. If a child restraint with one of these problems or any defect which has not been recognized with an official recall is found, it is important to notify officials responsible for defect investigations. To report a defect, call the National Highway Traffic Safety Administration (NHTSA) at 888-327-4236 or 800-424-9393 or go to <http://www-odi.nhtsa.dot.gov/ivoq>.
3. Recall wording, including manufacturer contact information, has been clarified and updated. The “Problem” is described clearly and briefly. The wording under “Action Needed” is based on current information supplied by the manufacturer instead of the original recall notice, which may contain ambiguous or obsolete information.
4. Model names are listed alphabetically. For ease of use and accuracy, all recalls are grouped by the model name of the restraint. Model numbers are also listed, if provided by the manufacturer.
5. All child restraint models made in the past 10 years, with or without a recall, are listed (models without a recall are at the end of each manufacturer’s section). If the model name is not found on the list, the child restraint should not be used.

# Child Restraint Manufacturer Recalls and Free Replacement Parts

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
<b>4Moms 912 Fort Duquesne Blvd., Pittsburgh PA 15222 888-614-6667 www.4Moms.com</b>				
4Moms	Self-Installing Car Seat (1032)	7/1/16 - 10/31/16	Due to an overly tight rivet on safety seat, safety seat may not attach correctly to base, increasing risk of injury during a crash.	Call 4Moms at 888-614-6667 for a free replacement safety seat. <b>BASE IS NOT AFFECTED.</b>
<b>4Moms models with no recalls, replacement parts, or warnings: none</b>				
<b>Aidia, Inc. 1459 18<sup>th</sup> St., San Francisco, CA 94107 866-328-8661 www.aidiaproducts.com</b>				
<b>Aidia models with no recalls, replacement parts, or warnings: Explorer, Pathfinder, Scout.</b>				
<b>Angel Guard Products, Inc. (c/o Mercury Distributing, 7001 Wooster Pike, Medina, OH 44256 800-815-6330) www.angel-guard.com</b>				
<b>Angel Guard model with no recalls, replacement parts, or warnings: AngelRide Infant Car Bed</b>				
<b>Aprica 3 Glenlake Parkway, Atlanta, GA 30328, 888-927-7422 www.aprica.com</b>				
<b>Aprica models with no recalls, replacement parts, or warnings: none.</b>				
<b>Aria Child, Inc. – See Goodbaby USA</b>				
<b>Baby Jogger 4110 Premier Dr., High Point NC 27265 1-800-241-1848 www.babyjogger.com</b>				
<b>Baby Jogger models with no recalls, replacement parts, or warnings: City Go 2, City Go Air, City Turn, City View</b>				
<b>Baby Trend 1607 S. Campus Ave. Ontario CA 91761 800-328-7363 www.babytrend.com</b>				
Baby Trend	Hybrid 3-in-1 Combination Booster Seat – Desert Blue, FB49E14A	12/6/21	LATCH webbing may fray, reducing its strength, causing a potential failure to restrain the child restraint.	Baby Trend will provide owners with a replacement LATCH assembly strap free of charge. Call 1-800-328-7363.
Baby Trend	Hybrid LX 3-in-1 Centennial FB58181 and Kiwi FB48417	FB58181 mfd. on 7/23/16, FB48417 mfd. on 7/14/16	Center rivet on harness adjuster may fail if child weighs more than 40 lbs., increasing risk of injury during a crash.	Call 1-800-328-7363 for free replacement safety seat or refund.
<b>Baby Trend models with no recalls, replacement parts, or warnings: Ally 35, Baby Trend Booster, Cover Me 4-in1, EZ Flex-Loc, EZ Flex-Loc 32, EZ-Lift 35 Plus, EZ Lift 35 Pro, EZ-Loc, Euro Sport, Flex-Loc, Inertia, PROtect Elite, PROtect Premiere/Sport, PROtect Yumi Booster, PROtect Yumi 2-in-1, Secure 35, Secure Lift 35, Secure Snap 35, Secure Snap Gear 32, Trooper 3-in1.</b>				
<b>Bergeron Health Care, 15 South Second Street, Dolgeville, NY 13329, 800-371-2778, www.adaptivemall.com</b>				
<b>Bergeron model with no recalls, replacement parts, or warnings: Special Tomato</b>				
<b>Britax Child Safety, 13501 So. Ridge Dr., Charlotte, NC 28273, 888-427-4829, www.britaxusa.com</b>				
Britax	Advocate ClickTight E1A025Q, E9LT95N, E9LT95Q, E9LT95Z	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.
Britax	BOB B-Safe 35 All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	Boulevard ClickTight E1A015Q, E1A016A, E1A016H, E1A135Q, E9LT85Q, E9LT85S, E9LT86A, E9LT86F, E9LT86G, E9LT86H	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.

Britax	B-Safe 35 All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Travel System All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 Travel System All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Elite All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 Elite All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Elite Travel System All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	Marathon ClickTight E1A005R, E1A006B, E1A116L, E9LT71Q, E9LT75R, E9LT76B, E9LT76L, E9LT76N, E9LT76P, EXA116L	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.
<b>Britax models with no recalls, replacement parts, or warnings:</b> Advocate, Advocate ClickTight ARB, Advocate 2013/G4, Boulevard ClickTight ARB, Boulevard 2013, B Safe, B Safe Gen 2,, B Safe Gen 2 Fl;exFit, B Safe Gen 2 FlexFit Plus, B Safe Ultra, Cypress, Endeavours, Essentials Allegiance, Essentials Emblem, Essentials Skyline, Frontier 85, Frontier 85 SICT, Frontier 90, Grow with You ClickTight/ClickTight Plus, Highpoint, Highway, Highway 65, Marathon CS, Marathon 70 G3, Marathon 2013, Midpoint, One4Life Clicktight, Parkway (all models), Pavilion 2013, Pinnacle 90, Pioneer 70, Poplar, Roundabout 50, Roundabout 55 G 3, Roundabout 2013, Skyline, Willow Aspen/Alpine, Willow SC.				
<b>BubbleBum, 7380 Sand Lake Road, Suite 500, Orlando, FL 32819, 800-969-6586, www.bubblebum.us</b>				
<b>BubbleBum models with no recalls, replacement parts, or warnings:</b> BubbleBum Booster				
<b>Carfoldio 10685-B Hazelhurst Dr. #17695 Houston TX 77043 www.mifold.com</b>				
<b>Carfoldio models with no recalls, replacement parts or warnings:</b> Hifold, Mifold, Mifold Comfort, Mifold One, Mifold Sport				
<b>Car Seat Specialty - See Team-Tex America</b>				
<b>Century Baby – See Graco</b>				
<b>Chicco, 1842 William Penn Way, Ste. 101, Lancaster, PA 17601, 877-424-4226, www.chiccousa.com</b>				
<b>Chicco models with no recalls, replacement parts, or warnings:</b> Fit2, Fit4, Fold & Go i-Size, GoFit, GoFit Plus, KeyFit, KeyFit 30, KeyFit 30 Magic, KeyFit 35, KeyFit Strada, KidFit Booster, MyFit/LE/ZipAir, NextFit/IX/Sport, NextFit Zip/Max, NextFit Zip Air, One Fit				
<b>Clek Inc., 12 Upjohn Road, Suite 1, Toronto, Ontario M3B 2V9, Canada 866-656-2462, clekinc.com</b>				
Clek	Filo FL15, FL16, FL17, FL18, FL19	All manufactured before May 21, 2021	Child may pick foam from cushion under seat pad, creating a choking hazard.	Clek will provide molded plastic insert that prevents access to the foam, free of charge.

Clek	Foonf FO12, FO13, FO14, FO15, FO16, FO17, FO18, FO19.	All manufactured before May 21, 2021	Child may pick foam from cushion under seat pad, creating a choking hazard.	Clek will provide molded plastic insert that prevents access to the foam, free of charge.
Clek	Liing LG19U1	All manufactured before September 15, 2020	Small portion of canopy support may break off, creating a choking hazard.	Clek will provide a replacement canopy support, free of charge.
Clek	Liing LG19U1	All manufactured before February 22, 2021	Labels on seat cover or infant insert may come apart in small pieces, creating a choking hazard.	Clek will provide a replacement seat cover or infant insert, free of charge.
Clek	Liingo LGO20U1	All manufactured before September 15, 2020	Small portion of canopy support may break off, creating a choking hazard.	Clek will provide a replacement canopy support, free of charge.
Clek	Liingo LGO20U1	All manufactured before February 22, 2021	Labels on seat cover or infant insert may come apart in small pieces, creating a choking hazard.	Clek will provide a replacement seat cover or infant insert, free of charge.
Clek	Olli OL12U2	January 20, 2020 – May 10, 2022	Label showing correct installation is missing.	Clek will mail owners a new label, free of charge.
Clek	Ozzi	March 1, 2020 – May 10, 2022	Label showing correct installation is missing.	Clek will mail owners a new label, free of charge.
<b>Clek models with no recalls, replacement parts, or warnings: Oobr</b>				
<b>Columbia Medical – See also Inspired by Drive</b>				
<b>Columbia models with no recalls, replacement parts, or warnings: #2000, #2500, Spirit (#2400)</b>				
<b>Combi USA, 3520 Westinghouse Blvd., Suite B, Charlotte, NC 28273, 800-992-6624, www.combiusa.com</b>				
Combi	BabyRide 378099	May 1, 2016 to August 31, 2019	Harness adjuster strap fails minimum strength requirements, which could lead to lack of protection from harness.	No remedy at this time. Contact Combi customer service by e-mail: customerservice@combiusa.com
Combi	Coccoro 8220	January 1, 2009 to June 29, 2016	If installed forward facing with a lap-only belt, excessive force may be transferred to the child in a crash, increasing the risk of injury.	Call 888-232-3294 for free cover for bottom of seat to reduce child’s risk of injury during a crash.
<b>Combi models with no recalls, replacement parts, or warnings: Dakota, Kobuk, Kobuk Air-Thru, Navette 22, Shuttle 33, Shuttle 35.</b>				
<b>Compass - See Tomy International.</b>				
<b>Convoid (ETAC), 2830 California St., Torrance, CA 90503 844-876-6245, www.convoid.com</b>				
<b>Convoid (ETAC) models with no recalls, replacement parts, or warnings: Carrot 3, Carrot Booster Seat</b>				
<b>Cosco - See Dorel Juvenile Group.</b>				
<b>Cybox (a Goodbaby International Company) 560 Harrison Ave., Ste. 411, Boston MA 02118 877-242-5676 www.cybox-online.com/US</b>				

Cybox	Aton	3/29/17- 1/4/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybox	Aton 2	3/29/17-10/27/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybox	Aton M	3/1/18-11/1/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybox	Aton Q	3/13/17-1/3/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybox	Cloud Q	7/6/17-10/20/20	Harness adjuster strap may fray, thus losing strength, increasing risk of injury during a crash.	CTP/CYBEX will mail owners a replacement central harness adjuster strap assembly and installation instructions, free of charge.
Cybox	Sirona M 518000211, 518000385, 518000387, 518002145, 518002149, 518002151, 518002153.	11/3/17-8/31/18	Child may pick pieces of foam from safety seat headrest pad, creating a choking hazard.	Cybox will provide a kit with instructions on how to seal the headrest, free of charge.



<b>Cybox models with no recalls, replacement parts, or warnings:</b> Aton G, Aton G Swivel, Cloud G, Cloud G Lux, Eternis, Sirona S, Solution B-Fix, Solution B2 Fix+ Lux, Solution M Fix, Solution Q Fix, Solution Q2 Fix, Solution Z Fix, X Fix Q				
<b>Diono LLC, 418 Valley Ave. NW, Suite 100, Puyallup, WA 98371, 855-463-4666, www.diono.com</b>				
Diono	Cambria 2 31200-US-01 31201-US-01 31202-US-01	9/5/2020 to 11/30/20	Headrest may separate from backrest during a crash.	Diono will provide replacement backrest with headrest assembly free of charge. Call 855-463-4666.
Diono	Olympia, Pacifica, Radian R100, Radian R120, Radian RXT, Rainier	11/25/13 to 9/5/17	If installed forward facing and untethered with lap-only belt, child may suffer chest injury in a crash.	Call 855-463-4666 for updated instruction manual, energy-absorbing pad, and new chest clip.
<b>Diono or Sunshine Kids models with no recalls, replacement parts, or warnings:</b> Cambria, Everett NXT, Hip, Monterey, Monterey 4DXT, Monterey 5iST FixSafe, Monterey XT, Radian models 3QX, 3QXT, 3r, 3rX, 3rXT, 3RXT Safe, 65, 65SL, 80, 80SL, QXT+, XT, XTSL, Rainier 2aX, Rainier 2aXT, Santa Fe, Snug Seat Pilot, Solana, Solana 2				
<b>Dorel Juvenile Group, 2525 State St., Columbus, IN 47201, 800-544-1108, www.djgusa.com</b>				
Note: <b>Dorel</b> is the parent company for <b>Cosco, Eddie Bauer, Maxi-Cosi, Safety 1<sup>st</sup>, Alpha Elite, and Alpha Sport</b> brands. Some models are marketed with multiple names.				
Dorel China America	Babideal Storm Booster Seat BC901BPXL	2/28/19 only	Label attached to fabric cover may not have the required safety warnings and instructions.	Call 877-657-9546 for a compliant replacement cover.
Dorel	Dream Ride, Dream Ride Ultra	Many older seats have been recalled. Do not use if past expiration date or if date is unknown.		
Dorel	Eddie Bauer	See specific model name.		
Dorel	Maxi-Cosi Coral XP, IC313	5/1/20-2/28/23	Owners are advised to only use the inner carrier of the Coral XP when it is attached to the outer carrier and installed with or without the base. The child seat inner carrier is not sufficient to restrain a child without the use of the outer carrier.	Dorel will offer a refund or replace the child seat, free of charge. Owners may contact Dorel's customer service at 1-877-657-9546 or CoralXPRecall@djgusa.com. Owner notification letters are expected to be mailed April 7, 2023.
Dorel	Maxi-Cosi Infant base, IC335	5/1/20-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546.
Dorel	Maxi-Cosi Mico Luxe +, IC370	1/1/22-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Maxi-Cosi Mico XP, IC336, IC338	9/1/20-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com

Dorel	Maxi-Cosi Mico XP Max, IC337	1/1/21-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Maxi-Cosi Travel Systems	Adorra, Gia, Tayla XP, Zelia2 Max	May include Maxi-Cosi Mico XP model IC336. If so, lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Maxi-Cosi Travel Systems	Mara XT	May include Maxi-Cosi Coral XP model IC313. If so, lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Maxi-Cosi Pria 70 CC133BGW, CC133BWL, CC133BWJL, CC133DCHI, CC133DCN	1/1/19 to 7/31/19	Failed FMVSS 213 when used with lap-only belt without tether strap attached for child over 65 lbs. Owners should be certain they have registered the seat with Dorel Juvenile Group.	Call 877-657-9546 to register seat & get free recall remedy kit with replacement instruction booklet and labels (forward-facing internal harness weight limit of the car seat to 65 lbs. and the height limit to 49 in.) Owners using or planning use for a child 65 lbs. or 40 in. or more can request free Maxi-Cosi Rodi Sport Booster (for children 40-100 lbs. & 43-57 in.)
Dorel	Maxi-Cosi Pria 85, Pria 85 Max: all models.	1/1/19 to 8/17/21	Failed FMVSS 213 for child over 65 lbs. when used with lap-only belt without tether strap attached. Owners should be certain they have registered the seat with Dorel Juvenile Group.	Call 877-657-9546 to register seat & get free recall remedy kit with replacement instruction booklet and labels (forward-facing internal harness weight limit of the car seat to 65 lbs. and the height limit to 49 in.). Owners using or planning use for a child 65 lbs. or 40 in. or more can request free Maxi-Cosi Rodi Sport Booster (for children 40-100 lbs. & 43-57 in.)
Dorel	Safety 1 <sup>st</sup> Secure Tech Infant base, IC372	All before 3/1/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com



Dorel	Safety 1 <sup>st</sup> onBoard 35 Secure Tech, IC351	5/1/22-2/28/23	Lower connectors may fail. Install child restraint only with safety belt until a new base can be provided by the company.	Dorel will contact registered owners and provide a new compliant base. Customers with questions may call 1-877-657-9546 or send an email to retractablelatchrecall@Djgusa.com
Dorel	Safety 1st	See specific model name.		
<b>Dorel models with no recalls, replacement parts, or warnings:</b> Able65, Advance 70 Air+, Advance EX 65 Air+, Advance SE or LX 65 Air +, Adjust 'n Go, Alpha Elite 65, Apex 65, Apt 40 RF, APT 50, Aquos 65, Boost A Pak, Boost Air Protect, Chart Air 65, Comfort 35, Comfort High Back Booster, Comfort Ride, Comfy Convertible, Commuter, Complete Air 65, Complete Air 70, Complete Voyager, Continuum, Deluxe Backed BPB, Deluxe Harness 65, Deluxe Highback 65, Designer, Destination, Dream Ride SE, Easy Elite, EasyFit 65, Elite 80 Air+, Elite 100 Air +, enRoute, Essential Air, EverFit, Finale, Getaway, Go Hybrid, Grand Explorer, Grow and Go (all models), Guide 65, High Rider, Incognito, Light 'N Comfy, Maxi-Cosi Cosi 35, Maxi-Cosi Emme 360, Maxi-Cosi Lux, Maxi-Cosi Magellan, Maxi-Cosi Magellan Max, Maxi-Cosi Magellan LiftFit, Maxi-Cosi Mico 30, Maxi-Cosi Mico Max Plus, Maxi-Cosi Mico Max 30, Maxi-Cosi Mico XP, Maxi-Cosi Prezi, Maxi- Cosi Pria 3-in-1 (65 lbs. ff), Maxi-Cosi Pria Sport, Maxi-Cosi Rodi (all models) Maxi-Cosi RodiFix, Maxi-Cosi RodiSport, Maxi-Cosi Romi, Maxi-Cosi Vello 65, Maxi-Cosi Vello 70, Mighty Fit 65 LX, DX 3-in-1, Multi Fit 3-in-1, Multi Fit EX Air, onBoard Insta-LATCH DLX, onBoard 35 Air (all models), onBoard 35 LT, onBoard35 Secure Tech, onSide Air Convertible, OnLook 3-in-1, Peri 180, Protek, Rightway, Rise, Rumi Air, Safety 1 <sup>st</sup> Boost & Go, Safety 1 <sup>st</sup> EverSlim, Safety 1 <sup>st</sup> Greener Baby Comfort Ride, Safety 1 <sup>st</sup> Scenera 40RF, Safety 1 <sup>st</sup> TriMate/TriFit, Scenera Next, Scenera Versa-Fit OHB, Sport, Stack It!, Store 'N Go, Summit, Summit 65, Summit Deluxe, Top Side Booster, Traveler, Trio Fit, Ventura, Vista, XRS 65.				
<b>Dream On Me, 170 Circle Drive North, Piscataway NJ 08854, 732-748-1300, www.dreamonme.com</b>				
<b>Dream On Me models with no recalls, replacement parts, or warnings:</b> Coupe backless booster, Deluxe highback booster, Mia Moda Certo (see also recall under Mia Moda)				
<b>Easycarseat</b> (Inflatable booster available online). According to NHTSA, the manufacturer states that all of the boosters sold in the U.S. were withdrawn.				
<b>Eddie Bauer - See Dorel Juvenile Group.</b>				
<b>Evenflo (a Goodbaby International company), 225 Byers Rd Miamisburg, OH 45342, 800-233-5921, www.evenflo.com</b>				
Evenflo	Evolve 34411700	2/26/15 to 2/9/16	Child can reach & release button loosening seat harness, a risk for injury. <b>If child has discovered how to release adjuster</b> , stop using seat.	Call 800/233-5921 for free repair kit & front adjuster components.
Evenflo	Evolve 34411741	5/27/15 to 2/9/16	Child can reach & release button loosening seat harness, a risk for injury. <b>If child has discovered how to release adjuster</b> , stop using seat.	Call 800/233-5921 for free repair kit & front adjuster components.
Evenflo	Momentum 65, 65 LX, 65 DLX	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.
Evenflo	SureRide, SureRide Deluxe, Titan 65	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.

Evenflo	Symphony 65, 65 E3, LX, DLX	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to <a href="http://www.safety.evenflo.com">www.safety.evenflo.com</a> for replacement screw.
Evenflo	Transitions 34411686, 34411695, 34411029	12/18/14 to 1/29/16	Child can reach & release button loosening seat harness, a risk for injury. <b>If child has discovered how to release adjuster</b> , stop using seat.	Call 800/233-5921 for new bottom seat pad & front adjuster components. Important: view video at <a href="http://www.transitions.evenflo.com">www.transitions.evenflo.com</a> .
<b>Evenflo models with no recalls, replacement parts, or warnings:</b> Advanced LiteMax 35, All4One, All4One DLX, Amp, Chase 2-in-1, Chase Plus 2-in1, Embrace 35 Advanced (w/SensorSafe), EveryFit/Every Kid, Every Stage DLX, Generations, Generations 65, GoTime, LiteMax 35, LiteMax DLX, LiteMax Sport, Maestro Sport, Nurture, NurtureMax, ProSeries LiteMaxRight Fit (all models), Revolve 360, SafeMax All-in-One, SafeMax RFO, SecureRide 35, Serenade, Slim, Shyft DualRide, Revolve Extend, Revolve Sightseer (highback booster), Sonus 50, Sonus 65, Spectrum, Stratos, Titan Elite, Titan Sport, Traditions, Tribute Sport, Triumph Advance 50, Triumph Advance 65, Vision.				
<b>EZ-ON Products LLC, 605 Commerce Way West, Jupiter, FL 33458, 800-323-6598, <a href="http://www.ezonpro.com">www.ezonpro.com</a></b>				
<b>EZ-ON Products LLC models with no recalls, replacement parts, or warnings:</b> Vests and Harnesses				
<b>GOBOOSTER – All models sold within US have been withdrawn, per NHTSA.</b>				
<b>Goodbaby USA 560 Harrison Ave. Boston MA 02118 844-543-2020 <a href="http://GBchildusa.com">GBchildusa.com</a></b>				
<b>Goodbaby USA models with no recalls, replacement parts or warnings:</b> Asana 35, Asana 35AP, Asana 35 DLX/LTE, Idan, Phil&Teds Alpha Protect, Aria Child/Urbini Asenti, Urbini Omni, Urbini Petal, Urbini Presti, Urbini Touri, Urbini Sonti.				
<b>Graco Children’s Products, 150 Oaklands Blvd, Exton, PA 19341, 800-345-4109 <a href="http://www.gracobaby.com">www.gracobaby.com</a>.</b>				
Graco	Extend2Fit 1954477	11/27/15 to 1/20/16	Information on recline label (upright for infant; reclined for older child) risks injury. Check labels on sides of seat to determine that one side is all English, other side, all Spanish.	If languages are mixed on either side of seat, call 1-800-345-4109 for replacement label.
Graco	Milestone 191030, 1923980, 1926538, 1926539	7/9/15 to 10/9/15	Label missing directive to install child restraint using lower anchors or safety belt.	Contact Graco at 800-345-4109 for free replacement label.
Graco	TurboBooster 1963973	3/8/16 to 4/2/16	Instructions don’t state that booster must be securely belted to vehicle at all times, even when booster is not occupied.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1963974	12/22/15 to 3/30/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1963975	12/22/15 to 3/17/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1963976	2/17/16 to 3/24/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1967886	1/13/16 to 4/5/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1975173	3/29/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.

<b>Graco models with no recalls, replacement parts, or warnings.</b> 4Ever (all models), Affix, Affix w/Safety Surround, Argos 65, Argos 80 Elite, Assura, Atlas 65, Babyjogger CityTurn, Century Baby BoostOn, Century Baby Carry On 35, Century Baby Carry On 35 LX, Century Baby Drive On, Colorz, Connex, Contender 65, Contender Go, Contender Slim, Extend2Fit Platinum, Extend2Fit 3-in1, Extend2Fit 3-in-1 w/Anti Rebound Bar, Platinum, Extend2Fit True Shield 3-in1, Fit4Me 65, Grows4Me, Head Wise 65, Infant Safe Seat, Landmark/Milestone 3-in-1, MySize 65, Nautilus 65 LX/DLX, Nautilus 80 Elite, Nautilus SnugLock Grow, Nautilus 2.0 LX, Nautilus, Premier SnugRide SnugFit 35 Elite, Premier SnugRide SnugFit LoadLeg, Sequence 65 Platinum, SnugLock DLX, Recline N' Ride, RightGuide Seat Belt Trainer, Sequel 65, Sequence 65, Size4Me 65, SlimFit 3-in-1, SlimFit 3 in 1 Platinum, SnugRide Click Connect 30, SnugRide Click Connect 35, SnugRide SnugLock 30, SnugRide 35 DLX LoadLeg, SnugRide 35 Lite, SnugRide Lite Elite, SnugRide SnugFit 35, SnugRide SnugLock 35 (all models), SnugRide SnugLock Extend2Fit, Tranzitions, Tranzitions SnugLock 3-in-1, TrioGrow SnugLock, TriRide, Tru3Fit ARB, TurboGo Folding Booster, TurboBooster Grow, TurboBooster LX backless LATCH, TurboBooster Stretch, TurboBooster TakeAlong, TurboBooster 2.0 LX, Turn2Me.				
<b>Harmony Juvenile Products, 1600 53rd Street, North Bergen, NJ 07047, 877-306-1001, www.harmonyjuvenile.com</b>				
Harmony Juvenile	Big Boost Deluxe	11/1/15 to 6/24/17	Tests showed excessive chest forces which could occur to a child during a crash.	Call Harmony customer service at 877/306-1001 for next steps.
<b>Harmony models with no recalls, replacement parts, or warnings:</b> Baby Armor, Carpooler, Cruz, Defender 360, Dreamtime Comfort, DreamTime Elite with LATCH, Folding Travel Booster, LiteRider, Olympian, Transit, Transit Deluxe, V6 Highback, Youth Booster, Youth Booster Elite with LATCH.				
<b>hauck Fun for Kids, 212 A Wilkinson Rd., Brampton, Ont., L6T 4M4 Canada 905 455 5888</b>				
<b>hauck Fun for Kids models with no recalls, replacement parts, or warnings:</b> iCoo, iGuard, PROsafe 35				
<b>hiccapop, 160 Alamo Plaza, Unit 590, Alamo CA 94507 888-442-2266 www.hiccapop.com</b>				
<b>hiccapop models with no recalls, replacement parts, or warnings:</b> UberBoost				
<b>IMMI (Also See SafeGuard) 18881 IMMI Way Westfield, Indiana 46074 317-896-9531 www.imminet.com</b>				
<b>IMMI Models with no recalls, replacement parts or warnings:</b> Go Combination Child Seat				
<b>Inspired by Drive 11724 Willake St. Santa Fe Springs CA 90670 800-454-6612 www.inspiredbydrive.com</b>				
<b>Inspired by Drive models with no recalls, replacement parts or warnings:</b> Spirit, Spirit APS, Spirit IPS, Spirit Plus				
<b>Jané USA, P.O. Box 410007, San Francisco, CA 94141, 415-824-1237, www.janeusa.com</b>				
<b>Jané USA models with no recalls, replacement parts, or warnings:</b> Indy Plus, Montecarlo R1, Team Plus				
<b>Jeffco or LaRoche models with no recalls, replacement parts, or warnings:</b> Grizzly Bear, Polar Bear, Teddy Bear				
<b>J J Cole - See Tomy</b>				
<b>Kiddy, http://www.kiddy.de/blog/us/ info@kiddyuk.com</b>				
<b>Kiddy models with no recalls, replacement parts, or warnings:</b> Cruiserfix Pro, Cruiser 3				
<b>KidsEmbrace, 4830 Rusina Rd., Suite B, Colorado Springs, CO 80907, 866-947-3287, www.kidsembrace.com</b>				
<b>KidsEmbrace models with no recalls, replacement parts, or warnings:</b> Combination seat, Toddler Booster, Fun Ride				
<b>Kids ii, 333 Piedmont Rd. NE, Ste. 1800, Atlanta GA 30305 770-551-0442 www.kidsii.com</b>				
<b>Kids ii models with no recalls, replacement parts, or warnings:</b> Ingenuity InTrust 35				
<b>LaRoche - See Jeffco Fibres</b>				
<b>Learning Curve - See Tomy International.</b>				
<b>Lil Fan 17401 Tiller Ct., Ste. A, Westfield IN 46074 317-804-9160 www.lilfan.com</b>				
<b>Lil Fan models with no recalls, replacement parts, or warnings:</b> Box Seat, Club Seat				
<b>Lilly Gold 5468 Maple Ridge Ct., Minnetonka MN 55343 800-829-1625 www.lillygold.com</b>				
<b>Lilly Gold products with no recalls, warnings, or replacement parts:</b> Sit 'N' Stroll				
<b>Little Tikes 2180 Barlow Rd. Hudson OH 44326 800-321-0183 www.littletikes.com</b>				
<b>Little Tikes products with no recalls, warnings, or replacement parts:</b> Highback Booster, Backless Booster, Hip				
<b>Maxi-Cosi - See Dorel</b>				
<b>Merritt Manufacturing, P. O. Box 17152, Indianapolis, IN 46217, 317-409-0148, www.merrittcarseat.com</b>				

Merritt Manufacturing	Angel Ride Car Bed	8/8/19 to 10/24/19	Harness may not be sewn properly where buckle is attached.	Call 317/409-0148 to order free replacement harness.
<b>Merritt Manufacturing models with no recalls, replacement parts, or warnings:</b> Chamberlain, Churchill, Hope Car Bed, Jefferson, Roosevelt, Wallenberg				
<b>Nania - See Team Tex America</b>				
<b>Nuna Baby Essentials Inc., 70 Thousand Oaks Blvd., Morgantown, PA 19543, 855-686-2872 www.nuna.eu/USA/index</b>				
<b>Nuna model with no recalls, replacement parts, or warnings:</b> AACE, Exec, Pipa, Pipa Aire RX, Pipa Lite, Pipa Lite R, Pipa Lite RX, Pipa RX, Pipa Urbn, Rava, Revv, Relx (base for Pipa RX and Pipa Lite R)				
<b>Orbit Baby Inc., 5437 Central Avenue, Suite 10, Newark, CA 94560, 877-672-2229, www.orbitbaby.com</b>				
<b>Orbit Baby Inc. models with no recalls, replacements parts, or warnings:</b> Infant G2/Infant G3, Infant G5, Orbit Toddler/Toddler G2/Toddler G3 (see above for information about bases), Toddler G5				
<b>Peg Perego U.S.A., 3625 Independence Dr., Fort Wayne, IN 46808, 800-671-1701, us.pegperego.com</b>				
Peg Perego	Primo Viaggio	All models with stroller base that has front bar	Stroller use: To prevent possibility of baby's fall due to incorrect placement of seat on stroller, make sure that front bar is installed on stroller and that seat is latched firmly to stroller with two hooks. Test by yanking seat toward front of stroller.	
<b>Peg Perego models with no recalls, replacement parts, or warnings:</b> Primo Viaggio 4-35, Primo Viaggio 4-35 Nido, Primo Viaggio Convertible, Primo Viaggio Convertible Kinetic, Primo Viaggio Lounge, Primo Viaggio SIP ES 30-30, Primo Viaggio SIP 5-70, Primo Viaggio Urban Mobility, Viaggio Flex 120, Viaggio Shuttle Plus				
<b>Phil&amp;Teds – See Goodbaby</b>				
<b>Porsche Cars of North America. Contact Britax.</b>				
<b>Porsche models with no recalls, replacement parts, or warnings:</b> Baby Seat, Junior Seat G1, Junior Seat Plus G2, G3.				
<b>ProRider model with no recalls, replacement parts, or warnings:</b> CNS Booster				
<b>R82 (ETAC), 2830 California St., Torrance, CA 90503 844-876-6245, www.convoid.com</b>				
<b>R82 (ETAC) models with no recalls, replacement parts, or warnings:</b> Pilot, Quokka, Stingray Swing-out, Wallaroo				
<b>Recaro Child Safety Systems North America, 1600 Harmon Rd., Auburn Hills, MI 48326, 888-973-2276 us.recaro-cs.com</b>				
<b>Recaro models with no recalls, replacement parts, or warnings:</b> Euro, Performance Booster, Performance Coupe, Performance Crossover, Performance Racer/Rally, Performance Ride, Performance Roadster, Performance Sport, ProBooster, ProRide, Vivo, Vivo Lite.				
<b>Safe Traffic System Inc., 10201 Pacific Ave. Franklin Park IL 847-233-0365, www.safetrafficsystem.com</b>				
<b>Safe Traffic System models with no recalls, replacement parts, or warnings:</b> Ride Safer Vests (all sizes), Delighter booster, TravelSmarter Booster				
<b>SafeGuard, 18881 US 31 North, P.O. Box 408, Westfield, IN 46074, 800-586-7839, www.safeguardseat.com</b>				
<b>SafeGuard models with no recalls, replacement parts, or warnings:</b> SafeGuard, SafeGuard Go.				
<b>Safety Angel/Safe Start, P.O. Box 740151, Boynton Beach, FL 33474, 561-732-1233, www.safetyangel.com</b>				
<b>Safety Angel model with no recall:</b> Ride Ryte				
<b>Safety 1<sup>st</sup> - See Dorel Juvenile Group</b>				
<b>Sammons Preston Rolyan, 1000 Remington Blvd, Bolingbrook, IL 60440, 800-323-5547, www.sammonspreston.com</b>				
<b>Sammons Preston Rolyan models with no recalls, replacement parts, or warnings:</b> Tumble Forms Carrie Seats				
<b>Simple Parenting 168 E Main St. Prospect Park NJ 07508 862-240-1755 www.happykidssmartparents.com</b>				
<b>Simple Parenting products with no recalls, warnings or replacement parts:</b> Doona				
<b>Sentry Baby Products, 6660 Delmonico Dr., Ste. D470 Colorado Springs CO 80919 719-212-6016 www.sentrybabyproducts.com</b>				
<b>Sentry Baby Products models with no recalls, replacement parts, or warnings:</b> Guardimals				

<b>smartridr 1321 Upland Dr., Ste. 10963 Houston TX 77043 800-317-8029 www.whizrider.com</b>			
smartridr	WhizRider	All models	September 2022 smartridr sent a letter to all their customers to inform them that the WhizRider is not a child restraint system or booster seat as defined by FMVSS 213. No recall was issued.
<b>smartridr models with no recalls, replacement parts, or warnings: none</b>			
<b>Snug Seat. (now R82) Box 1739, Matthews, NC 28106, 800-336-7684, www.R82.com</b>			
<b>Snug Seat models with no recalls, replacement parts, or warnings: Hippo, Pilot, SS1000, Snug Seat Car Bed, Traveler Plus EL</b>			
<b>Snugli, 225 Byers Rd Miamisburg, OH 45342, 1-800-374-3603, www.snugli.com</b>			
Snugli	All-in-One	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall) Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.
<b>Snugli models with no recalls, replacement parts, or warnings: Infant Car Seat</b>			
<b>Summer Infant, 1275 Park East Drive, Woonsocket, RI 02895, 800-268-6237, www.summerinfant.com</b>			
<b>Summer Infant models with no recalls, replacement parts, or warnings: Affirm 335, Prodigy</b>			
<b>Team-Tex America (formerly Car Seat Specialty), P. O. Box 3194, Rock Hill, SC 29732, 877-912-1313</b>			
<b>Team-Tex models with no recalls, replacement parts, or warnings: Beline, Dream, Dreamway SP, HighRide</b>			
<b>Teutonia USA, 150 Oaklands Boulevard, Exton, PA 19341, 877-838-8664, www.teutoniausa.com</b>			
<b>Teutonia models with no recalls, replacement parts, or warnings: T-Tario 32, T-Tario 35</b>			
<b>Thomashilfen, 309 South Cloverdale Street, Unit B 12, Seattle WA 98108, 866-870-2122, www.thomashilfen.com (Previously Exomotion)</b>			
<b>Distributor for Recaro Monza Nova 2 Reha, Recaro ProSport Reha, Recaro Defender Reha (no recalls)</b>			
<b>Tomy International, 1111 W. 22nd Street, Suite 320, Oak Brook, IL 60523, 1-800-704-8697, www.tomy.com (Previously Learning Curve)</b>			
<b>Tomy, Learning Curve, and Compass models with no recalls, replacement parts, or warnings: Via (all models), Compass Folding Adjustable Boosters (all models), all True Fit convertible models</b>			
<b>Triple Play Products - See Lilly Gold</b>			
<b>UPPAbaby, 60 Sharp Street, Hingham, MA 02043, 781-413-3000 www.uppababy.com</b>			
UPPAbaby	Knox	2019 to 2020	UPPAbaby voluntarily recalled the first Knox models (manufactured 2019 to 2020), because it was found to easily tip over when installed rearfacing. UPPAbaby offered a refund and pulled all Knox seats off the shelf. A redesigned version was released in 2021.
<b>UPPAbaby models with no recalls, replacement parts, or warnings: Aria, Alta, Alta V2, Mesa, Mesa Max, Mesa V2</b>			
<b>Urbini – See Goodbaby USA</b>			
<b>WAYB, 99 Pasadena Ave., Ste. 11 South Pasadena CA 91030 888-924-9292 wayb.com</b>			
WAYB	Pico	2/1/19 to 8/23/19	Stop using if headrest tubes or pins connecting to tubes are broken or cracked. Call 888/924-9292 for a redesigned headrest. Manufacturer states breakage occurs due to damage in transit outside the vehicle or overloading in installation or use.
<b>WAYB models with no recalls, replacement parts, or warnings: none</b>			

**BMW of North America** is recalling 7,162 2016 BMW 5 Series sedans to fix a problem with the child-restraint lower anchor system. The 2016 BMW 5 Series models are listed on the following page. The affected vehicles have an inboard lower anchor for child restraints on the left rear seat that may have been bent downwards, preventing the child seat from fully engaging both lower anchors, thus, increasing a child's risk of injury in a crash. The month and year of manufacture can be found on the VIN sticker on the inside driver door panel. Caregivers installing a restraint here should use the safety belt instead, until the lower anchor is inspected/repaired by BMW.

**BMW of North America** announced an additional recall on July 12, 2016 affecting certain X3 and X4 models, manufactured between 2011 and 2016. Please see table below.

**Nissan North America** has announced a recall on its 2013-2016 Sentras. Please see table on following page.

**Volkswagen North America** has announced a recall on some model year 2018 Atlas SUVs. Please see table on following page.

BMW of North America, LLC	528i Sedan	8/15/15 to 9/14/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	528i xDrive Sedan	7/20/15 to 9/11/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535i Sedan	7/20/15 to 9/8/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535i xDrive Sedan	7/20/15 to 9/9/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535d xDrive Sedan	7/21/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	550i Sedan	7/20/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	550i xDrive Sedan	7/20/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535d Sedan	7/20/15 to 9/8/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	M5 Sedan	7/21/15 to 9/11/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	X3 xDrive28d	2015-2017 model year, manufactured 3/10/14 to 3/31/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525-7417.



BMW of North America, LLC	X3 sDrive28i, X3 xDrive28i, X3 xDrive35i	2011-2017 model year, manufactured 7/2/10 to 4/14/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	X4 xDrive28i, X4 xDrive35i, X4 xDriveM40i	2015-2017 model year, manufactured 3/3/14 to 4/15/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525-7417.
Nissan North America, Inc.	Sentra	2013-2016 model year (approximately 620,000 vehicles)	Front passenger seat safety belt bracket may become deformed if child restraint is installed, which may cause air bag not to shut off.	As of 5/8/16, Nissan North America, Inc. has not found a solution for the problem. Do not install any child restraint in this seating position.
Volkswagen North America	Atlas SUVs with 2 <sup>nd</sup> row bench seats	2018 model year, manufactured 11/7/16 to 6/5/18 (approximately 54,357 vehicles)	Owner's manual lacks a warning to avoid installing safety seats with rigid lower connectors OR bases wider than 12.6 inches in the center location because of damage to or potential release of the center or adjacent side safety belt buckle.	Dealers will inspect and possibly replace such buckles and give an owner's manual supplement on child passenger safety.

## Switchable Retractor Recall

Some Autoliv switchable retractors in a variety of 2021 and 2022 vehicles and manufactured between October 26, 2020, and January 27, 2021 do not stay locked when switched to automatic locking mode. Take the vehicle back to the dealership for a free repair.

Temporarily, use a different seating position OR use with the lock-off on your safety seat OR if the child's weight is under that listed for your safety seat lower connectors, connect to the lower anchors, and always attach the top tether strap for any forward-facing safety seat.

The following 2021 and 2022 vehicles and seating positions are affected:

- 2021 **Audi** S3, A4, S4, A6, S6, RS6, A7, S7, RS7, A8, and S8 sedans (middle rear seat belts only)
- 2021 **Audi** A5, S5, and RS5 coupes and convertibles, and A6 Allroad wagons (middle rear seat belts only)
- 2021 **Audi** Q3, Q5, SQ5, Q7, SQ7, Q8, SQ8, RSQ8, and E-Tron SUVs (middle rear seat belts only)
- 2021 **Bentley** Bentayga SUVs (front passenger belt only)
- 2021 **BMW** 2 Series, 3 Series, M3, 4 Series, M4, and 5 Series sedans, coupes, and convertibles
- 2021 **BMW** X1 and X2 SUVs
- 2021 **BMW** Z4 coupes (front passenger seat only)
- 2021 and 2022 **Ford** Transit and Ford Transit Connect SUVs (front passenger belt only)
- 2021 **Lamborghini** Urus SUVs (middle rear belt only)
- 2021 **Mini Cooper** and Mini Clubman hatchbacks and convertibles (front passenger seat only)
- 2022 **Mitsubishi** Outlander SUVs (front passenger and second-row belts)
- 2021 **Nissan** Rogue Sport SUVs (front passenger and rear outer belts only)
- 2021 **Porsche** 911 coupes and convertibles
- 2021 **Porsche** Panamera and Taycan sedans
- 2021 **Rolls-Royce** Cullinan SUVs
- 2021 **Rolls-Royce** Ghost and Phantom sedans
- 2021 **Toyota** Supra coupes (front passenger seat only)
- 2021 **Volkswagen** ID.4 SUVs (rear seat belts only)

## Recalls for Safety Seat Products Noncompliant with FMVSS 213

December 29, 2022: JD E-Commerce America Limited (Joybuy Express). NHTSA has determined a recall on all Marainbow Portable Infant Safe Seat **and materially similar child seats**. The installation labels display incorrect instructions. The child seat design prohibits these models and all similar from being installed properly. As such, these child seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard 213, "Child Restraint Systems." The child seat may be improperly installed, increasing the risk of injury in a crash. **Joybuy Express** will provide a refund to purchasers. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Joybuy Express customer service at 1-302/426-4543.



JOYBUY CARTOON STROLLER CUSHION  
JOYBUY FARFI RUST-PROOF BOOSTER  
JOYBUY FOLD WATERPROOF CAR SEAT  
JOYBUY MARAINBOW PORTABLE INFANT  
JOYBUY PORTABLE BABY COVER SEAT  
JOYBUY PORTABLE BABY INFANT SAFE SEAT  
JOYBUY YDX ANTI-SLIP CUSHION  
JOYBUY TWOWOOD RUST PROOF BOOSTER

JOYBUY PORTABLE INFANT SAFE SEAT  
JOYBUY PRETTY COMY CAR SEAT  
JOYBUY PORTABLE BABY SAFETY SEAT  
JOYBUY QCTIME ANTI-SLIP CUSHION  
JOYBUY THICK PORTABLE CAR SEAT  
JOYBUY TWOWOOD ANTI-SLIP CUSHION