

## **List of Recalls and Replacement Parts for Child Restraints**

**June 11, 2020**

There are no new recalls. New safety seats not on recall have been added. Safety seats not on recall are listed under each manufacturer. Products discontinued or companies out of business for 10 years or more are not listed. Call SafetyBeltSafe U.S.A. with inquiries on older models.

### **How can you tell if your safety seat is safe?**

Make sure that the expiration date stamped on the plastic has not passed and it has never been used in a crash. You can't be sure about the history of a used seat unless you got it from a friend or relative. You will need the detailed instruction booklet (it can be ordered from the manufacturer if it is missing) to check that the seat has all of its parts and to find out how to use it correctly. Check for possible damage, such as cracks in the plastic, frayed straps, stiff buckles or harness adjusters. If the safety seat passes all of these criteria, you still need to check for possible recalls.

### **What is a safety seat recall?**

Just like cars and other products, a safety seat may be "recalled" because of a defect that could injure your child. Manufacturers are required to fix the problem free of charge. If your seat is recalled, be sure to get it fixed right away.

### **Does the safety seat have to be sent back?**

Not usually. Most problems can be fixed by replacing a part that the manufacturer will send you for free. Sometimes, with an older seat or when the company is out of business, you will need to take it to a special recycling center (go to [www.carseat.org/recycling\\_la.html](http://www.carseat.org/recycling_la.html) for more info) or, if none is available in your area, destroy the seat to make sure it is not picked up by someone and used by another child. Break it with a sledgehammer, crush it, or take it completely apart and mark it "not for use as a safety seat" before throwing it away wrapped securely in a heavy trash bag.

### **Should I keep using a recalled seat?**

Many defects are minor, but some are quite serious. All problems should be corrected as soon as possible. Unless you have another seat, you should go on using the recalled one while you are waiting for the repair kit. Using a recalled safety seat almost always is safer than letting your child ride in a safety belt only.

### **How to check your safety seat for recalls**

1. Look up the name of the manufacturer.
2. Look up the name of your specific model. Important: the model name may not be found anywhere on the seat, and many safety seats have similar model names. Some rear-facing-only seats are sold as a part of a stroller system. Since stroller model names are not included on this list, it is necessary to determine the name of the corresponding rear-facing-only seat to be sure all recalls and warnings have been found. Some manufacturers have style names (i.e., Oshkosh, Disney characters, etc.) sewn on the fabric or used in promotional materials. These names are used for more than one product and cannot be used to determine whether or not the seat has a recall. If you are not sure of the exact name of your seat, check the Color Pictorial Guide to Child Restraints (you may order a hard copy or license to print from SafetyBeltSafe U.S.A.) or contact the manufacturer or SafetyBeltSafe U.S.A. to help you identify it.
3. If you are sure of the EXACT name of your seat, you are ready to look it up on the recall list. Every model certified by the manufacturer to meet U.S. safety standards and made within the last 10 years is on this list, either with a recall or under the "no recall" section at the end of each manufacturer's section.
4. If your model has a recall listed, you need to compare the date of manufacture of your particular seat with the dates affected by the recall. The date is computer-generated on a paper sticker attached to the side or the back of the seat. Disregard dates on tags attached to the fabric cover or pre-printed in the corner of certification or instruction labels. For some recalls, you also will need to check the model number, which is found on the same sticker as the date. If the date sticker is missing or the date is not clearly marked, assume that all possible recalls apply to your seat. Even if no recall applies, do not use a seat if it has passed its expiration date (specified by the manufacturer in the instruction booklet, usually 4 to 10 years from the date of manufacture), which usually is stamped into the plastic shell.

## Special Features of the *SafetyBeltSafe* U.S.A. List of Recalls and Replacement Parts for Child Restraints

1. New recalls are added to this list as soon as they can be verified. Recall Update Service subscribers receive notification by e-mail. To verify that a printed copy of this list is current, go to [www.carseat.org](http://www.carseat.org) and click on Recalls (left frame).
2. Voluntary customer notification campaigns, special warnings, and additional replacement parts available from manufacturers are included on the list. Some of these are not widely announced and are provided for the benefit of parents and child restraint checkers. The bracketed phrase [Not publicized] indicates usage advice or repair kit availability that has been verified with but not announced by the manufacturer. If a child restraint with one of these problems or any defect which has not been recognized with an official recall is found, it is important to notify officials responsible for defect investigations. To report a defect, call the National Highway Traffic Safety Administration (NHTSA) at 888-327-4236 or 800-424-9393 or go to <http://www-odi.nhtsa.dot.gov/ivoq>.
3. Recall wording, including manufacturer contact information, has been clarified and updated. The “Problem” is described clearly and briefly. The wording under “Action Needed” is based on current information supplied by the manufacturer instead of the original recall notice, which may contain ambiguous or obsolete information.
4. Model names are listed alphabetically. For ease of use and accuracy, all recalls are grouped by the model name of the restraint. Model numbers are also listed, if provided by the manufacturer.
5. All child restraint models made in the past 10 years, with or without a recall, are listed (models without a recall are at the end of each manufacturer’s section). If the model name is not found on the list, the child restraint should not be used.

### Child Restraint Manufacturer Recalls and Free Replacement Parts

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
<b>4Moms 912 Fort Duquesne Blvd., Pittsburgh PA 15222 888-614-6667 <a href="http://www.4Moms.com">www.4Moms.com</a></b>				
4Moms	Self-Installing Car Seat (1032)	7/1/16 - 10/31/16	Due to an overly tight rivet on safety seat, safety seat may not attach correctly to base, increasing risk of injury during a crash.	Call 4Moms at 888-614-6667 for a free replacement safety seat. BASE IS NOT AFFECTED.
<b>4Moms models with no recalls, replacement parts, or warnings: none</b>				
<b>Aidia, Inc. 1459 18<sup>th</sup> St., San Francisco, CA 94107 866-328-8661 <a href="http://www.aidiaproducts.com">www.aidiaproducts.com</a></b>				
<b>Aidia models with no recalls, replacement parts, or warnings: Explorer, Pathfinder, Scout.</b>				
<b>Angel Guard Products, Inc. (c/o Mercury Distributing, 7001 Wooster Pike, Medina, OH 44256 800-815-6330) <a href="http://www.angel-guard.com">www.angel-guard.com</a></b>				
<b>Angel Guard model with no recalls, replacement parts, or warnings: AngelRide Infant Car Bed</b>				
<b>Aprica 3 Glenlake Parkway, Atlanta, GA 30328, 888-927-7422 <a href="http://www.aprica.com">www.aprica.com</a></b>				
Aprica	A30	7/1/11-4/30/12	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 877-766-7470 for replacement buckle, or visit <a href="http://GracoBuckleRecall.com">GracoBuckleRecall.com</a>
<b>Aprica models with no recalls, replacement parts, or warnings: none.</b>				
<b>Aria Child, Inc. – See Goodbaby USA</b>				
<b>Baby Jogger 4110 Premier Dr., High Point NC 27265 1-800-241-1848 <a href="http://www.babyjogger.com">www.babyjogger.com</a></b>				

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Baby Jogger	City Go safety seats (BJ64510, BJ64529), bases (BJ80400, BJ61500), City Mini Travel Systems (BJ72510), Vue Lite Travel Systems (BJ70411, BJ70424, BJ70431)	11/3/14 to 4/30/15	Information on some labels, instruction manuals, and/or registration cards is missing, sized incorrectly, out of order, or has the wrong background color.	Call Baby Jogger at 800-241-1848 for a free replacement safety seat.
<b>Baby Jogger models with no recalls, replacement parts, or warnings: City View</b>				
<b>Baby Trend 1607 S. Campus Ave. Ontario CA 91761 800-328-7363 www.babytrend.com</b>				
Baby Trend	Hybrid LX 3-in-1 Centennial FB58181 and Kiwi FB48417	FB58181 mfd. on 7/23/16, FB48417 mfd. on 7/14/16	Center rivet on harness adjuster may fail if child weighs more than 40 lbs., increasing risk of injury during a crash.	Call 1-800-328-7363 for free replacement safety seat or refund.
Baby Trend	Trendz Fastback 3-in-1 #FB60070; FB60408	10/1/11 to 7/31/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 1-800-328-7363 for replacement buckle.
<b>Baby Trend models with no recalls, replacement parts, or warnings: Ally 35, Baby Trend Booster, EZ Flex-Loc, EZ Flex-Loc 32, EZ-Loc, Euro Sport, Flex-Loc, Inertia, PROtect Elite, PROtect Premiere/Sport, PROtect Yumi Booster, PROtect Yumi 2-in-1, Secure 35, Secure Snap Gear 32.</b>				
<b>Bergeron Health Care, 15 South Second Street, Dolgeville, NY 13329, 800-371-2778, www.adaptivemall.com</b>				
<b>Bergeron model with no recalls, replacement parts, or warnings: Special Tomato</b>				
<b>Britax Child Safety, 13501 So. Ridge Dr., Charlotte, NC 28273, 888-427-4829, www.britaxusa.com</b>				
Britax	Advocate 70 CS	7/1/2010 to 8/31/2011	A screw and washer in the base joint connector may be missing (does not affect performance). [Not a recall]	Call Britax for more information and replacement kit, if needed.
Britax	Advocate 70-G3 E9LG81A, E9LG83N, E9LG83P, E9LG83X, E9LG83Y, E9LL21A, E9LL23P, E9LL23Y	6/1/2012 to 8/31/2012	Material of HUGS chest pads is too soft, which could be a choking hazard.	Monitor child and call for replacement pads.
Britax	Advocate ClickTight E1A025Q, E9LT95N, E9LT95Q, E9LT95Z	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.
Britax	BOB B-Safe 35 All models	11/1/15-5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	Boulevard 70, Boulevard 70 CS	7/1/2010 to 8/31/2011	A screw and washer in the base joint connector may be missing (does not affect performance). [Not a recall]	Call Britax for more information and replacement kit, if needed.
Britax	Boulevard 70-G3 E9LJ91A, E9LJ91M, E9LJ91S, E9LJ92E, E9LJ93P, E9LJ93S, E9LK91A	6/1/2012 to 8/31/2012	Material of HUGS chest pads is too soft, which could be a choking hazard.	Monitor child and call for replacement pads.
Britax	Boulevard ClickTight E1A015Q, E1A016A, E1A016H, E1A135Q, E9LT85Q, E9LT85S, E9LT86A, E9LT86F, E9LT86G, E9LT86H	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Britax	B-Safe 35 All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Travel System All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 Travel System All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Elite All models	10/1/2014 to 7/1/2015	Carry handle may develop cracks in, under, or around handle grip, which may lead to handle fracturing.	Do NOT carry by handle. Call 800-683-2045 for repair kit.
Britax	B-Safe 35 Elite All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	B-Safe 35 Elite Travel System All models	11/1/15- 5/31/17	Center tab on chest clip may break, posing a choking hazard to child.	Call 833-474-7016 for repair kit.
Britax	Marathon 70	7/1/2010 to 8/31/2011	A screw and washer in the base joint connector may be missing (does not affect performance). [Not a recall]	Call Britax for more information and replacement kit, if needed.
Britax	Marathon ClickTight E1A005R, E1A006B, E1A116L, E9LT71Q, E9LT75R, E9LT76B, E9LT76L, E9LT76N, E9LT76P, EXA116L	8/1/2014 to 7/29/2015	Red harness adjustment button may remain in release position after harness is tightened, enabling shoulder straps to loosen.	Call Britax for repair kit that includes lubricant to apply once only, directly to harness adjustment button.
Britax	Pavilion 70-G3 E9LK31A, E9LK31Q, E9LK32D, E9LK32Z, E9LK33Q, E9LL11A, E9LL11Q, E9LL12D, E9LL12Z	6/1/2012 to 8/31/2012	Material of HUGS chest pads is too soft, which could be a choking hazard.	Monitor child and call for replacement pads.
Britax	Roundabout 55	7/1/2010 to 8/31/2011	A screw and washer in the base joint connector may be missing (does not affect performance). [Not a recall]	Call Britax for more information and replacement kit, if needed.

**Britax models with no recalls, replacement parts, or warnings:** Advocate, Advocate ClickTight ARB, Advocate CS, Advocate 2013/G4, Boulevard ClickTight ARB, Boulevard CS, Boulevard 2013, B-Safe, B Safe Ultra, Diplomat, Dual Fit, Endeavours, Essentials Allegiance, Essentials Emblem, Essentials Skyline, Frontier 85, Frontier 85 SICT, Frontier 90, Grow with You ClickTight/ClickTight Plus, Highpoint, Highway, Highway 65, Marathon CS, Marathon 70 G3, Marathon 2013, Midpoint, One4Life Clicktight, Parkway (all models), Pavilion 2013, Pinnacle 90, Pioneer 70, Roundabout 50, Roundabout 55 G 3, Roundabout 2013, Skyline.

**BubbleBum, 7380 Sand Lake Road, Suite 500, Orlando, FL 32819, 800-969-6586, www.bubblebum.us**

**BubbleBum models with no recalls, replacement parts, or warnings:** BubbleBum Booster

**Carfoldio 10685-B Hazelhurst Dr. #17695 Houston TX 77043 www.mifold.com**

**Carfoldio models with no recalls, replacement parts or warnings:** Hifold, Mifold, Mifold One, Mifold Sport

**Car Seat Specialty - See Team-TEX America**

**Chicco, 1842 William Penn Way, Ste. 101, Lancaster, PA 17601, 877-424-4226, www.chiccousa.com**

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
<b>Chicco models with no recalls, replacement parts, or warnings:</b> Fit2, Fold & Go i-Size, GoFit, KeyFit, KeyFit 30, KeyFit 30 Magic, KeyFit Strada, KidFit Booster, MyFit/LE/ZipAir, NextFit/IX/Sport, NextFit Zip/Max, NextFit Zip Air				
<b>Clek Inc., 12 Upjohn Road, Suite 1, Toronto, Ontario M3B 2V9, Canada 866-656-2462, clekinc.com</b>				
<b>Clek models with no recalls, replacement parts, or warnings:</b> Fllo, Foonf, Liing, Olli, Oobr, Ozzi				
<b>Columbia Medical – See also Inspired by Drive</b>				
<b>Columbia models with no recalls, replacement parts, or warnings:</b> #2000, #2500, Spirit (#2400)				
<b>Combi USA, 3520 Westinghouse Blvd., Suite B, Charlotte, NC 28273, 800-992-6624, www.combiusa.com</b>				
Combi	Coccoro 8220	January 1, 2009 to December 31, 2012	Webbing (without seat) tore partially in static test because of embedded plastic button that keeps buckle tongues from sliding out of reach. Complete restraint system complies with all requirements.	Call 844-697-1690 for free harness replacement kit. Continue using seat until new harness is received.
Combi	Coccoro 8220	January 1, 2009 to June 29, 2016	If installed forward facing with a lap-only belt, excessive force may be transferred to the child in a crash, increasing the risk of injury.	Call 888-232-3294 for free cover for bottom of seat to reduce child's risk of injury during a crash.
Combi	Zeus 360 8836	February 1, 2009 to May 31, 2012	Webbing (without seat) tore partially in static test because of embedded plastic button that keeps buckle tongues from sliding out of reach. Complete restraint system complies with all requirements.	Call 844-697-1690 for free harness replacement kit. Continue using seat until new harness is received.
<b>Combi models with no recalls, replacement parts, or warnings:</b> Dakota, Kobuk, Kobuk Air-Thru, Navette 22, Shuttle 33, Shuttle 35.				
<b>Compass - See Tomy International.</b>				
<b>Convoid (ETAC), 2830 California St., Torrance, CA 90503 844-876-6245, www.convoid.com</b>				
<b>Convoid (ETAC) models with no recalls, replacement parts, or warnings:</b> Carrot 3, Carrot Booster Seat				
<b>Cosco - See Dorel Juvenile Group.</b>				
<b>Cybex (a Goodbaby International Company) 560 Harrison Ave., Ste. 411, Boston MA 02118 877-242-5676 www.cybex-online.com/US</b>				
<b>Cybex models with no recalls, replacement parts, or warnings:</b> Aton, Aton 2, Aton Q, Aton M, Cloud Q, Eternis, Sirona M, Sirona S, Solution M Fix, Solution Q Fix, Solution Q2 Fix, X Fix Q				
<b>Diono LLC, 418 Valley Ave. NW, Suite 100, Puyallup, WA 98371, 855-463-4666, www.diono.com</b>				
Diono	Olympia, Pacifica, Radian R100, Radian R120, Radian RXT, Rainier	11/25/13 to 9/5/17	If installed forward facing and untethered with lap-only belt, child may suffer chest injury in a crash.	Call 855-463-4666 for updated instruction manual, energy-absorbing pad, and new chest clip.
<b>Diono or Sunshine Kids models with no recalls, replacement parts, or warnings:</b> Cambria, Cambria 2, Everett NXT, Hip, Monterey, Monterey 4DXT, Monterey XT, Radian models 3r, 3rX, 3rXT, 65, 65SL, 80, 80SL, XT, XTSL, Rainier 2aX, Rainier 2aXT, Santa Fe, Snug Seat Pilot, Solana, Solana 2				
<b>Dorel Juvenile Group, 2525 State St., Columbus, IN 47201, 800-544-1108, www.djgusa.com</b>				
Note: <b>Dorel</b> is the parent company for <b>Cosco, Eddie Bauer, Maxi-Cosi, Safety 1<sup>st</sup>, Alpha Elite, and Alpha Sport</b> brands. Some models are marketed with multiple names.				
Dorel	3-In-1	See Alpha Omega.		
Dorel	All in One	See Alpha Omega.		
Dorel China America	Babideal Storm Booster Seat BC901BPXL	2/28/19 only	Label attached to fabric cover may not have the required safety warnings and instructions.	Call 877-657-9546 for a compliant replacement cover.

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Dorel	Comfy Carry IC123FSM	5/1/11 to 4/30/12	Some seats were sold without detachable base containing the required LATCH system.	Call for base with LATCH system.
Dorel	Dream Ride, Dream Ride Ultra	Many older seats have been recalled. Do not use if past expiration date or if date is unknown.		
Dorel	Eddie Bauer	See specific model name.		
Dorel	High Back Booster (generic)	Note: Dorel identifies various models as "High Back Boosters," including several combination seats (used as child seat with harness or as booster after removing harness; with or without armrest; with front or rear harness adjuster) as well as boosters only (no harness included).		
Dorel	Olympian	See Touriva		
Dorel	onBoard 35 IC124FSM	5/1/11 to 4/30/12	Some seats were sold without detachable base containing the required LATCH system.	Call for base with LATCH system.
Dorel	Safety 1st	See specific model name.		
<b>Dorel models with no recalls, replacement parts, or warnings:</b> Able65, Advance 70 Air+, Advance EX 65 Air+, Advance SE or LX 65 Air +, Alpha Elite 65, Ambassador, Apex 65, Apt 40 RF, APT 50, Aquos 65, Boost A Pak, Boost Air Protect, Chart Air 65, Comfort High Back Booster, Comfort Ride, Comfy Convertible, Commuter, Complete Air, Complete Air 65, Complete Air 70, Complete Voyager, Continuum, Deluxe Backed BPB, Deluxe Harness 65, Deluxe Highback 65, Designer, Destination, Dream Ride SE, Easy Elite, EasyFit 65, Elite 80 Air+, Elite 100 Air +, enRoute, Essential Air, EverFit, Finale, Go Hybrid, Grand Explorer, Grow and Go, Grow and Go EX Air, Guide 65, High Rider, Incognito, Light 'N Comfy, Maxi-Cosi Cosi35, Maxi-Cosi Magellan Max 5, Maxi-Cosi Mico AP/Mico Nxt, Maxi-Cosi Mico 30, Maxi-Cosi Mico Max Plus, Maxi-Cosi Mico Max 30, Maxi-Cosi Prezi, Maxi-Cosi Pria 70 (all models), Maxi-Cosi Pria 85, Maxi-Cosi Pria 85 Max, Maxi-Cosi Rodi (all models) Maxi-Cosi RodiFix, Maxi-Cosi Vello 65, Maxi-Cosi Vello 70, Mighty Fit 3-in-1, Multi Fit 3-in-1, onBoard 35 Air (all models), onSide Air Convertible, Portable Car Seat, Protek, Rightway, Rise, Rumi Air, Scenera 40RF, Scenera Next, Scenera Versa-Fit OHB, Sport, Stack It!, Store 'N Go, Summit, Summit 65, Summit Deluxe, Top Side Booster, Traveler, Ventura, Vista, XRS 65.				
<b>Dream On Me, 170 Circle Drive North, Piscataway NJ 08854, 732-748-1300, www.dreamonme.com</b>				
<b>Dream On Me models with no recalls, replacement parts, or warnings:</b> Coupe backless booster, Deluxe highback booster, Mia Moda Certo (see also recall under Mia Moda)				
<b>Easycarseat</b> (Inflatable booster available online). According to NHTSA, the manufacturer states that all of the boosters sold in the U.S. were withdrawn.				
<b>Eddie Bauer - See Dorel Juvenile Group.</b>				
<b>Evenflo (a Goodbaby International company), 225 Byers Rd Miamisburg, OH 45342, 800-233-5921, www.evenflo.com</b>				
Evenflo	Big Kid Booster 30911173AD, 3091967AD, 30911118AD, 30911120D	Unknown. Shipped 8/6/12 to 9/18/12	Registration card and instruction manual are missing. Sticker on backrest: "Display Only. Not intended for sale."	Call for missing card and manual. If seat has been distributed by program, notify recipient.
Evenflo	Chase, Chase LX, DLX, Chase Select 306xxxx, 329xxxx	8/23/11 to 3/3/14	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 800-490-7591 or go to www.buckle.evenflo.com for replacement buckle.

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Evenflo	Embrace 35	12/2011-5/2013. <b>CHECK COLUMNS AT RIGHT FOR MODEL #'s</b>	May be difficult to release harness buckle, which could cause risk to child in emergency. Model #'s 30711365, 31511040, 31511323, 31511400, 3151198, 3151953, 31521138, 46811205, 46811237, 48111200, 48111215, <b>SEE COLUMN AT RIGHT FOR ADDITIONAL MODEL #s.</b>	Call 800-490-7591 or go to <a href="http://www.embracebuckle.evenflo.com">www.embracebuckle.evenflo.com</a> for replacement buckle. Additional model numbers: 48111215A, 48111218, 48111234, 48111235, 48111235A, 48111462, 48411391, 48411391D, 48411392, 48411504, 48411504D, 52911307A, 52921040, 55311138, 55311238, 55311292
Evenflo	Evolve 34411700	2/26/15 to 2/9/16	Child can reach & release button loosening seat harness, a risk for injury. <b>If child has discovered how to release adjuster</b> , stop using seat.	Call 800/233-5921 for free repair kit & front adjuster components.
Evenflo	Evolve 34411741	5/27/15 to 2/9/16	Child can reach & release button loosening seat harness, a risk for injury. <b>If child has discovered how to release adjuster</b> , stop using seat.	Call 800/233-5921 for free repair kit & front adjuster components.
Evenflo	Express 329xxx	10/31/11 to 3/3/14	See Chase listed above for details.	
Evenflo	Fresh Air	Refer to specific model name. Fresh Air is name of style/fabric.		
Evenflo	Maestro, Maestro Performance 310xxxx	8/22/11 to 10/17/13	See Chase listed above for details.	
Evenflo	Momentum 65, 65 LX, 65 DLX	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to <a href="http://www.safety.evenflo.com">www.safety.evenflo.com</a> for replacement screw.
Evenflo	Momentum 65, 65 LX, 65 DLX 385xxxx	3/4/13 to 8/26/13	See Chase listed above for details.	
Evenflo	Secure Kid, Secure Kid LX, DLX, 100/300/400, 308xxxx	12/13/11 to 3/3/14	See Chase listed above for details.	
Evenflo	SureRide, SureRide Deluxe, Titan 65	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to <a href="http://www.safety.evenflo.com">www.safety.evenflo.com</a> for replacement screw.
Evenflo	SureRide DLX 371xxxx	6/20/12 to 10/17/13	See Chase listed above for details.	
Evenflo	Symphony 65, 65 E3, LX, DLX	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to <a href="http://www.safety.evenflo.com">www.safety.evenflo.com</a> for replacement screw.
Evenflo	Symphony 65, 65 E3, LX, DLX 345xxxx, 346xxxx	10/2/12 to 8/26/13	See Chase listed above for details.	

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Evenflo	Titan 65 71xxxx	6/20/12 to 10/17/13	See Chase listed above for details.	
Evenflo	Transitions 34411686, 34411695, 34411029	12/18/14 to 1/29/16	Child can reach & release button loosening seat harness, a risk for injury. <b>If child has discovered how to release adjuster</b> , stop using seat.	Call 800/233-5921 for new bottom seat pad & front adjuster components. Important: view video at <a href="http://www.transitions.evenflo.com">www.transitions.evenflo.com</a> .
<b>Evenflo models with no recalls, replacement parts, or warnings:</b> Amp, Chase 2-in-1, Embrace 35 Advanced (w/SensorSafe), Every Kid, Every Stage DLX, Generations, Generations 65, Lite Max 35, Maestro Sport, Nurture, Right Fit (all models), SafeMax All-in-One, SecureRide 35, Serenade, Sightseer (highback booster), Sonus 50, Sonus 65, Spectrum, Stratos, Symphony, Titan Elite, Titan Sport, Traditions, Tribute Sport, Triumph Advance 50, Triumph Advance 65, Vision.				
<b>EZ-ON Products LLC, 605 Commerce Way West, Jupiter, FL 33458, 800-323-6598, www.ezonpro.com</b>				
<b>EZ-ON Products LLC models with no recalls, replacement parts, or warnings:</b> Vests and Harnesses				
<b>GOBOOSTER – All models sold within US have been withdrawn, per NHTSA.</b>				
<b>Goodbaby USA 560 Harrison Ave. Boston MA 02118 844-543-2020 GBchildusa.com</b>				
<b>Goodbaby USA models with no recalls, replacement parts or warnings:</b> Asana 35, Asana 35AP, Asana 35 DLX/LTE, Idan, Phil&Teds Alpha Protect, Aria Child/Urbini Asenti, Urbini Omni, Urbini Petal, Urbini Presti, Urbini Touri, Urbini Sonti.				
<b>Graco Children’s Products, 150 Oaklands Blvd, Exton, PA 19341, 800-345-4109 www.gracobaby.com.</b>				
Graco	Argos 70, Argos 70 Elite	5/1/11 to 7/31/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 877-766-7470 for replacement buckle, or visit <a href="http://GracoBuckleRecall.com">GracoBuckleRecall.com</a>
Graco	Classic Ride 1812930	3/1/ 14 to 2/28/15	Labels missing information on location of instruction manual.	Call 1-800-345-4109 for replacement label.
Graco	Classic Ride 50	10/1/11 to 9/30/13; see Argos 70 listed above for details.		
Graco	ComfortSport 1794333, 1813040	3/1/ 14 to 2/28/15	Labels missing information on location of instruction manual.	Call 1-800-345-4109 for replacement label.
Graco	ComfortSport	10/1/10 to 9/30/13; see Argos 70 listed above for details.		
Graco	Extend2Fit 1954477	11/27/15 to 1/20/16	Information on recline label (upright for infant; reclined for older child) risks injury. Check labels on sides of seat to determine that one side is all English, other side, all Spanish.	If languages are mixed on either side of seat, call 1-800-345-4109 for replacement label.
Graco	Head Wise 70 w/Safety Surround	1/1/12 to 7/31/13 and 8/3/13; see Argos 70 listed above for details.		
Graco	Milestone 191030, 1923980, 1926538, 1926539	7/9/15 to 10/9/15	Label missing directive to install child restraint using lower anchors or safety belt.	Contact Graco at 800-345-4109 for free replacement label.
Graco	My Ride 65, My Ride 65 with Safety Surround	4/1/09 to 7/31/13, and 9/30/13; see Argos 70 listed above for details.		
Graco	My Ride 65	Model #s 1794334 (mfd. 5/20/14-7/15/14), 1813015 (mfd. 7/3/14-7/24/14), 1813074 (mfd. 6/20/14-7/27/14), 1853478 (mfd. 7/11/14-7/27/14), 1871689 (mfd. 7/5/14-7/24/14), 1872691 (mfd. 5/16/14-8/1/14), 1877535 (mfd. 5/26/14-7/27/14), and 1908152 (mfd. 7/23/14-7/27/14). Affected models also have “2014/06” on harness tag. These harnesses may fail in a crash. Contact Graco for a free replacement harness. 800-345-4109		



MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Graco	My Ride 70	5/1/12-7/31/13; See Argos 70 listed above for details.		
Graco	My Size 70	1/1/12 to 7/31/13, and 8/3/13; see Argos 70 listed above for details.		
Graco	Nautilus 3-in-1, Nautilus Elite, Nautilus Plus	10/1/07 to 7/31/13 and 8/19/13; see Argos 70 listed above for details.		
Graco	Ready Ride 1924519, 1924520	3/1/14 to 2/28/15	Labels missing information on location of instruction manual.	Call 1-800-345-4109 for replacement label.
Graco	Ready Ride	10/1/10 to 9/30/13	See Argos 70 listed above for details.	
Graco	Size4Me 70	1/1/12 to 7/31/13 and 8/3/13; see Argos 70 listed above for details.		
Graco	Smart Seat	12/1/10-9/30/13 and 10/9/2013, 12/25/2013, 1/10/2014; see Argos 70 listed above.		
Graco	SnugRide, SnugRide Classic Connect	3/1/11 to 5/31/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 877-766-7470 for replacement buckle.
Graco	SnugRide 30, SnugRide Classic Connect 30	7/1/10 to 1/31/13	See SnugRide, SnugRide Classic Connect listed above for details.	Call 877-766-7470 for replacement buckle.
Graco	SnugRide 35, SnugRide Classic Connect 35	5/1/11 to 1/31/13	See SnugRide, SnugRide Classic Connect listed above for details.	Call 877-766-7470 for replacement buckle.
Graco	SnugRide Click Connect 40	6/1/12 to 12/31/12	See SnugRide, SnugRide Classic Connect listed above for details.	Call 877-766-7470 for replacement buckle.
Graco	TurboBooster 1963973	3/8/16 to 4/2/16	Instructions don't state that booster must be securely belted to vehicle at all times, even when booster is not occupied.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1963974	12/22/15 to 3/30/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1963975	12/22/15 to 3/17/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1963976	2/17/16 to 3/24/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1967886	1/13/16 to 4/5/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
Graco	TurboBooster 1975173	3/29/16	See reason at TurboBooster 1963973 above.	Call 800-345-4109 for revised instruction booklet.
<b>Graco models with no recalls, replacement parts, or warnings.</b> 4Ever, 4Ever Deluxe, 4Ever Extend2Fit, Affix, Affix w/Safety Surround, AirBooster, Argos 65, Argos 80 Elite, Assura, Atlas 65, CarGo, Colorz, Connex, Contender 65, Fit4Me 65, Grows4Me, Head Wise 65, Infant Safe Seat, Landmark/Milestone 3-in-1, MySize 65, Nautilus 65 LX/DLX, Nautilus 80 Elite, Nautilus SnugLock DLX, Recline N' Ride, RightGuide Seat Belt Trainer, Sequel 65, Sequence 65, Size4Me 65, SlimFit 3-in-1, SnugRide 32, SnugRide Click Connect 30, SnugRide Click Connect 35, SnugRide SnugLock 30, SnugRide SnugLock 35 (all models), SnugRide SnugLock Extend2Fit, Tranzitions, TrioGrow SnugLock, TurboGo Folding Booster, TurboBooster Grow, TurboBooster TakeAlong.				
<b>Harmony Juvenile Products, 1600 53rd Street, North Bergen, NJ 07047, 877-306-1001, www.harmonyjuvenile.com</b>				
Harmony Juvenile	Big Boost Deluxe	11/1/15 to 6/24/17	Tests showed excessive chest forces which could occur to a child during a crash.	Call Harmony customer service at 877/306-1001 for next steps.

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
<b>Harmony models with no recalls, replacement parts, or warnings:</b> Baby Armor, Carpooler, Cruz, Defender 360, Dreamtime Comfort, Folding Travel Booster, LiteRider, Olympian, Transit, Transit Deluxe, V6 Highback, Youth Booster.				
<b>hauck Fun for Kids, 212 A Wilkinson Rd., Brampton, Ont., L6T 4M4 Canada 905 455 5888</b>				
<b>hauck Fun for Kids models with no recalls, replacement parts, or warnings:</b> iCoo, iGuard, PROsafe 35				
<b>hiccipop, 160 Alamo Plaza, Unit 590, Alamo CA 94507 888-442-2266 <a href="http://www.hiccipop.com">www.hiccipop.com</a></b>				
<b>hiccipop models with no recalls, replacement parts, or warnings:</b> UberBoost				
<b>IMMI (Also See SafeGuard) 18881 IMMI Way Westfield, Indiana 46074 317-896-9531 <a href="http://www.imminet.com">www.imminet.com</a></b>				
<b>IMMI Models with no recalls, replacement parts or warnings:</b> Go Combination Child Seat				
<b>Inspired by Drive 11724 Willake St. Santa Fe Springs CA 90670 800-454-6612 <a href="http://www.inspiredbydrive.com">www.inspiredbydrive.com</a></b>				
<b>Inspired by Drive models with no recalls, replacement parts or warnings:</b> Spirit, Spirit APS, Spirit IPS, Spirit Plus				
<b>Jané USA, P.O. Box 410007, San Francisco, CA 94141, 415-824-1237, <a href="http://www.janeusa.com">www.janeusa.com</a></b>				
<b>Jané USA models with no recalls, replacement parts, or warnings:</b> Indy, Indy Plus, Montecarlo R1, Team, Team Plus				
<b>Jeffco or LaRoche models with no recalls, replacement parts, or warnings:</b> Grizzly Bear, Polar Bear, Teddy Bear				
<b>J J Cole - See Tomy</b>				
<b>Kiddy, <a href="http://www.kiddy.de/blog/us/info@kiddyuk.com">http://www.kiddy.de/blog/us/info@kiddyuk.com</a></b>				
Kiddy USA	World Plus 51 100 WP	2/1/12 to 10/5/13 (all models ever produced)	Buckle tongue may not fully engage on affected seats.	Contact manufacturer for full refund of purchase price. Call 1-855-925-4339 for more information.
<b>Kiddy models with no recalls, replacement parts, or warnings:</b> Cruiserfix Pro, Cruiser 3				
<b>KidsEmbrace, 4830 Rusina Rd., Suite B, Colorado Springs, CO 80907, 866-947-3287, <a href="http://www.kidsembrace.com">www.kidsembrace.com</a></b>				
<b>KidsEmbrace models with no recalls, replacement parts, or warnings:</b> Combination seat, Toddler Booster, Fun Ride				
<b>Kids ii, 333 Piedmont Rd. NE, Ste. 1800, Atlanta GA 30305 770-551-0442 <a href="http://www.kidsii.com">www.kidsii.com</a></b>				
<b>Kids ii models with no recalls, replacement parts, or warnings:</b> Ingenuity InTrust 35				
<b>LaRoche - See Jeffco Fibres</b>				
<b>Learning Curve - See Tomy International.</b>				
<b>Lil Fan 17401 Tiller Ct., Ste. A, Westfield IN 46074 317-804-9160 <a href="http://www.lilfan.com">www.lilfan.com</a></b>				
<b>Lil Fan models with no recalls, replacement parts, or warnings:</b> Box Seat, Club Seat				
<b>Lilly Gold 5468 Maple Ridge Ct., Minnetonka MN 55343 800-829-1625 <a href="http://www.lillygold.com">www.lillygold.com</a></b>				
<b>Lilly Gold products with no recalls, warnings, or replacement parts:</b> Sit 'N' Stroll				
<b>Little Tikes 2180 Barlow Rd. Hudson OH 44326 800-321-0183 <a href="http://www.littletikes.com">www.littletikes.com</a></b>				
<b>Little Tikes products with no recalls, warnings or replacement parts:</b> Highback Booster, Backless Booster, Hip				
<b>Maxi-Cosi - See Dorel</b>				
<b>Merritt Manufacturing, P. O. Box 17152, Indianapolis, IN 46217, 317-409-0148, <a href="http://www.merrittcarseat.com">www.merrittcarseat.com</a></b>				
Merritt Manufacturing	Angel Ride Car Bed	8/8/19 to 10/24/19	Harness may not be sewn properly where buckle is attached.	Call 317/409-0148 to order free replacement harness.
<b>Merritt Manufacturing models with no recalls, replacement parts, or warnings:</b> Chamberlain, Churchill, Hope Car Bed, Jefferson, Roosevelt, Wallenberg				
<b>Nania - See Team Tex America</b>				
<b>Nuna Baby Essentials Inc., 70 Thousand Oaks Blvd., Morgantown, PA 19543, 855-686-2872 <a href="http://www.nuna.eu/USA/index">www.nuna.eu/USA/index</a></b>				
<b>Nuna model with no recalls, replacement parts, or warnings:</b> AACE, Exec, Pipa, Pipa Lite, Pipa Lite R, Pipa RX, Rava, Relx (base for Pipa RX and Pipa Lite R)				
<b>Orbit Baby Inc., 5437 Central Avenue, Suite 10, Newark, CA 94560, 877-672-2229, <a href="http://www.orbitbaby.com">www.orbitbaby.com</a></b>				

© SafetyBeltSafe U.S.A. PO Box 553 Altadena CA 91003 (310) 318-5111 [www.carseat.org](http://www.carseat.org) (800) 745-SAFE

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
Orbit Baby	G2 Car Seat Base ORB822000, Batch #A0840, A0860, A0880	3/20/13 to 7/20/13	StrongArm knob may detach or spin without tightening base.	Call to order repair kit. Use seat without base until base is repaired.
<b>Orbit Baby Inc. models with no recalls, replacements parts, or warnings:</b> Infant/Infant G2/Infant G3, Orbit Toddler/Toddler G2/Toddler G3 (see above for information about bases)				
<b>Peg Perego U.S.A., 3625 Independence Dr., Fort Wayne, IN 46808, 800-671-1701, us.pegperego.com</b>				
Peg Perego	Primo Viaggio	All models with stroller base that has front bar	Stroller use: To prevent possibility of baby's fall due to incorrect placement of seat on stroller, make sure that front bar is installed on stroller and that seat is latched firmly to stroller with two hooks. Test by yanking seat toward front of stroller.	
<b>Peg Perego model with no recalls, replacement parts, or warnings:</b> Primo Viaggio 4-35, Primo Viaggio 4-35 Nido, Primo Viaggio Convertible, Primo Viaggio Convertible Kinetic, Primo Viaggio SIP ES 30-30, Primo Viaggio SIP 5-70, Viaggio Flex 120, Viaggio Shuttle Plus				
<b>Phil&amp;Teds – See Goodbaby</b>				
<b>Porsche Cars of North America. Contact Britax.</b>				
<b>Porsche models with no recalls, replacement parts, or warnings:</b> Baby Seat, Junior Seat G1, Junior Seat Plus G2, G3.				
<b>ProRider 7818 S 212th St Ste. 106, Kent, WA 98032 800-414-5560 www.prorider.com</b>				
<b>ProRider model with no recalls, replacement parts, or warnings:</b> CNS Booster				
<b>R82 (ETAC), 2830 California St., Torrance, CA 90503 844-876-6245, www.convaid.com</b>				
<b>R82 (ETAC) models with no recalls, replacement parts, or warnings:</b> Pilot, Quokka, Wallaroo				
<b>Recaro Child Safety Systems North America, 1600 Harmon Rd., Auburn Hills, MI 48326, 888-973-2276 us.recaro-cs.com</b>				
Recaro	Performance RIDE, all models beginning with 333.01	1/15/13 to 6/9/15	Tether may detach from car seat during crash.	Retrofit kit will be provided by Recaro. Customers may also call 1-866-628-4750 to request retrofit kit.
Recaro	ProRIDE, all models beginning with 332.01	4/9/10 to 6/9/15	Tether may detach from car seat during crash.	Retrofit kit will be provided by Recaro. Customers may also call 1-866-628-4750 to request retrofit kit.
Recaro	ProSport (model numbers start with 385)	6/16/10 to 1/31/13	Excess head excursion if restraint is installed with lower anchors and not tethered.	Call mfr. for label & revised instructions; discontinue use of lower anchors when child reaches 40 lbs.
<b>Recaro models with no recalls, replacement parts, or warnings:</b> Como, Como G2, Euro, Performance Booster, Performance Coupe, Performance Crossover, Performance Racer/Rally, Performance Ride, Performance Roadster, Performance Sport, ProBooster, ProRide, Signo, Signo G2, Vivo, Vivo Lite, Young Sport.				
<b>Safe Traffic System Inc., 10201 Pacific Ave. Franklin Park IL 847-233-0365, www.safetrafficsystem.com</b>				
<b>Safe Traffic System models with no recalls, replacement parts, or warnings:</b> Ride Safer Vests, Delighter booster				
<b>SafeGuard, 18881 US 31 North, P.O. Box 408, Westfield, IN 46074, 800-586-7839, www.safeguardseat.com</b>				
<b>SafeGuard models with no recalls, replacement parts, or warnings:</b> SafeGuard, SafeGuard Go.				
<b>Safety Angel/Safe Start, P.O. Box 740151, Boynton Beach, FL 33474, 561-732-1233, www.safetyangel.com</b>				
<b>Safety Angel model with no recall:</b> Ride Ryte				
<b>Safety 1<sup>st</sup> - See Dorel Juvenile Group</b>				
<b>Sammons Preston Rolyan, 1000 Remington Blvd, Bolingbrook, IL 60440, 800-323-5547, www.sammonspreston.com</b>				
<b>Sammons Preston Rolyan models with no recalls, replacement parts, or warnings:</b> Tumble Forms Carrie Seats				

© SafetyBeltSafe U.S.A. PO Box 553 Altadena CA 91003 (310) 318-5111 www.carseat.org (800) 745-SAFE

MFR.	MODEL NAME (MODEL #)	DATES APPLICABLE	PROBLEM	ACTION REQUIRED
<b>Simple Parenting 168 E Main St. Prospect Park NJ 07508 862-240-1755 www.happykidssmartparents.com</b>				
<b>Simple Parenting products with no recalls, warnings or replacement parts: Doona</b>				
<b>Sentry Baby Products, 6660 Delmonico Dr., Ste. D470 Colorado Springs CO 80919 719-212-6016 www.sentrybabyproducts.com</b>				
<b>Sentry Baby Products models with no recalls, replacement parts, or warnings: Guardimals</b>				
<b>Snug Seat. (now R82) Box 1739, Matthews, NC 28106, 800-336-7684, www.R82.com</b>				
<b>Snug Seat models with no recalls, replacement parts, or warnings: Hippo, Pilot, SS1000, Snug Seat Car Bed, Traveler Plus EL</b>				
<b>Snugli, 225 Byers Rd Miamisburg, OH 45342, 1-800-374-3603, www.snugli.com</b>				
Snugli	All-in-One	2011-2015, select models	A screw on the harness adjuster, front & center below the adjuster strap, may detach or loosen. (Does not affect performance; not a recall)	Call 800-233-5921 (Evenflo) or go to www.safety.evenflo.com for replacement screw.
Snugli	All-in-One 346xxxx	10/2/12 to 8/26/13	May be difficult to release harness buckle, which could cause risk to child in emergency.	Call 800-490-7591 (Evenflo) or go to www.buckle.evenflo.com for replacement buckle.
Snugli	Booster 308xxxx	12/13/11 to 3/3/14	See All-in-One	
<b>Snugli models with no recalls, replacement parts, or warnings: Infant Car Seat</b>				
<b>Summer Infant, 1275 Park East Drive, Woonsocket, RI 02895, 800-268-6237, www.summerinfant.com</b>				
<b>Summer Infant models with no recalls, replacement parts, or warnings: Affirm 335, Prodigy</b>				
<b>Team-Tex America (formerly Car Seat Specialty), P. O. Box 3194, Rock Hill, SC 29732, 877-912-1313</b>				
<b>Team-Tex models with no recalls, replacement parts, or warnings: Beline, Dream, Dreamway SP, HighRide</b>				
<b>Teutonia USA, 150 Oaklands Boulevard, Exton, PA 19341, 877-838-8664, www.teutoniausa.com</b>				
<b>Teutonia models with no recalls, replacement parts, or warnings: T-Tario 32, T-Tario 35</b>				
<b>Thomashilfen, 309 South Cloverdale Street, Unit B 12, Seattle WA 98108, 866-870-2122, www.thomashilfen.com (previously Exomotion)</b>				
<b>Distributor for Recaro Monza Nova 2 Reha, Recaro ProSport Reha, Recaro Defender Reha (no recalls)</b>				
<b>Tomy International, 1111 W. 22nd Street, Suite 320, Oak Brook, IL 60523, 1-800-704-8697, www.tomy.com (previously Learning Curve)</b>				
<b>Tomy, Learning Curve, and Compass models with no recalls, replacement parts, or warnings: I 410, Via (all models), Compass Folding Adjustable Boosters (all models), all True Fit convertible models</b>				
<b>Triple Play Products - See Lilly Gold</b>				
<b>UPPAbaby, 60 Sharp Street, Hingham, MA 02043, 781-413-3000 www.uppababy.com</b>				
<b>UPPAbaby models with no recalls, replacement parts, or warnings: Alta, Mesa</b>				
<b>Urbini – See Goodbaby USA</b>				
<b>WAYB, 99 Pasadena Ave., Ste. 11 South Pasadena CA 91030 888-924-9292 wayb.com</b>				
WAYB	Pico	2/1/19 to 8/23/19	Stop using if headrest tubes or pins connecting to tubes are broken or cracked. Call 888/924-9292 for a redesigned headrest. Manufacturer states breakage occurs due to damage in transit outside the vehicle or overloading in installation or use.	
<b>WAYB models with no recalls, replacement parts, or warnings: none</b>				

**BMW of North America** is recalling 7,162 2016 BMW 5 Series sedans to fix a problem with the child-restraint lower anchor system. The 2016 BMW 5 Series models are listed on the following page. The affected vehicles have an inboard lower anchor for child restraints on the left rear seat that may have been bent downwards, preventing the child seat from fully engaging both lower anchors, thus, increasing a child's risk of injury in a crash. The month and year of manufacture can be found on the VIN sticker on the inside driver door panel. Caregivers installing a restraint here should use the safety belt instead, until the lower anchor is inspected/repaired by BMW.

**BMW of North America** announced an additional recall on July 12, 2016 affecting certain X3 and X4 models, manufactured between 2011 and 2016. Please see table below.

**Nissan North America** has announced a recall on its 2013-2016 Sentras. Please see table on following page.

**Volkswagen North America** has announced a recall on some model year 2018 Atlas SUVs. Please see table on following page.

BMW of North America, LLC	528i Sedan	8/15/15 to 9/14/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	528i xDrive Sedan	7/20/15 to 9/11/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535i Sedan	7/20/15 to 9/8/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535i xDrive Sedan	7/20/15 to 9/9/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535d xDrive Sedan	7/21/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	550i Sedan	7/20/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	550i xDrive Sedan	7/20/15 to 9/3/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	535d Sedan	7/20/15 to 9/8/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	M5 Sedan	7/21/15 to 9/11/15	See paragraph above.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	X3 xDrive28d	2015-2017 model year, manufactured 3/10/14 to 3/31/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525-7417.

BMW of North America, LLC	X3 sDrive28i, X3 xDrive28i, X3 xDrive35i	2011-2017 model year, manufactured 7/2/10 to 4/14/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525-7417.
BMW of North America, LLC	X4 xDrive28i, X4 xDrive35i, X4 xDriveM40i	2015-2017 model year, manufactured 3/3/14 to 4/15/16	Lower anchors may be damaged if child restraint is installed using rigid lower connectors, increasing risk of injury to child.	Owners should contact BMW Customer Service at (800) 525-7417.
Nissan North America, Inc.	Sentra	2013-2016 model year (approximately 620,000 vehicles)	Front passenger seat safety belt bracket may become deformed if child restraint is installed, which may cause air bag not to shut off.	As of 5/8/16, Nissan North America, Inc. has not found a solution for the problem. Do not install any child restraint in this seating position.
Volkswagen North America	Atlas SUVs with 2 <sup>nd</sup> row bench seats	2018 model year, manufactured 11/7/16 to 6/5/18 (approximately 54,357 vehicles)	Owner's manual lacks a warning to avoid installing safety seats with rigid lower connectors OR bases wider than 12.6 inches in the center location because of damage to or potential release of the center or adjacent side safety belt buckle.	Dealers will inspect and possibly replace such buckles and give an owner's manual supplement on child passenger safety.